
CURRENT FIRE SAFETY DESIGN ASPECTS OF COMMUTER AIRCRAFT (U) EVENTS ANALYSIS INC OAKTON VA R CLARKE ET AL. MAR 88 DOT/FAR/CT-87/32 DTFR03-86-C-00062 RD-R194 554 1/1 UNCLASSIFIED F/G 1/6 NL



OTIC_EILE_COPY

DOT/FAA/CT-87/32

FAA Technical Center

Atlantic City International Airport N.J. 08405

Current Fire Safety Design Aspects of Commuter Aircraft

AD-A194 554

Richard Clarke Deborah Kane Carla Stewart

EVENTS ANALYSIS, Inc. Oakton, Virginia 22124



March 1988

Final Report

This document is available to the U.S. public through the National Technical Information Service, Springfield, Virginia 22161.

DISTRIBUTION STATEMENT A

Approved for public releases
Distribution Unlimited



U.S. Department of Transportation
Federal Aviation Administration

AD-ALGUSS4 1. Inits and Submits CURRENT FIRE SAFETY DESIGN ASPECTS OF COMMUTER AIRCRAFT 7. Author's) Richard Clarke, Deborah Kane, Carla Stewart 1. Performing Organization Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 12. Securely Agency Name and Address U.S. Department of Transportation Technical Center Administration Technical Center	1. Report No.	2. Gevernment Accession No.	3, Recipient's Catalog No.
CURRENT FIRE SAFETY DESIGN ASPECTS OF COMMUTER AIRCRAFT Author's) Richard Clarke, Deborah Kane, Carla Stewart Performing Organization Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 Semissing Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 Author's) Supplementery Nates A Abstract is study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current per ation and aircraft most commonly delivered. These aircraft represent 880 of 1100 Immuter aircraft and probably will be the majority of the commuter fleet in the future. The terral is millar to those in large commercial aircraft. Among the ten aircraft two active and is a transfer two are der, piston powered aircraft, simple in design and materials applications. Of the other eight aircraft, two are no longer delivered. Four newer and larger designs feature, esterate bagsage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at the entry point. Thermoplastics and comment, with interior storage limited to bins at t	DOT/FAA/CT-87/32	AD-A 194 59	54
Asharest Richard Clarke, Deborah Kane, Carla Stewart Performing Organization Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 Semissing Agenty Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 ACT-350 ACT-350 ANalysest In Semissing Agenty Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 ACT-350 ACT-350 ACT-350 ACT-350 ACT-350 Activated to the majority of the commuter aircraft and probably will be the majority of the commuter fleet in the future. Terral transportation in application of terrials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials application of terrials similar to those in large commercial aircraft. Among the ten aircraft two are aircraft has a large interior with standing headroom. The others are much more commuter, with interior storage limited to bins at the entry point. Thermoplastics and consiste materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic third-blocking materials. Ston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other spit aircraft are turboprop aircraft using engine bleed air for cabin heating and cool: a caircraft are turboprop aircraft using engine bleed air for cabin heating and cool: a caircraft are unpressurized and four are pressurized. One new design has an optional cygen system using oxygen generators; the other aircraft use cylinder stored oxygen.	. Title and Subtitle		
Asharest Richard Clarke, Deborah Kane, Carla Stewart Performing Organization Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 Semissing Agenty Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 ACT-350 ACT-350 ANalysest In Semissing Agenty Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 ACT-350 ACT-350 ACT-350 ACT-350 ACT-350 Activated to the majority of the commuter aircraft and probably will be the majority of the commuter fleet in the future. Terral transportation in application of terrials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials application of terrials similar to those in large commercial aircraft. Among the ten aircraft two are aircraft has a large interior with standing headroom. The others are much more commuter, with interior storage limited to bins at the entry point. Thermoplastics and consiste materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic third-blocking materials. Ston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other spit aircraft are turboprop aircraft using engine bleed air for cabin heating and cool: a caircraft are turboprop aircraft using engine bleed air for cabin heating and cool: a caircraft are unpressurized and four are pressurized. One new design has an optional cygen system using oxygen generators; the other aircraft use cylinder stored oxygen.	CURRENT EXPE CAPTRY D	TECTON ACRECTE OF COMMETER A	March 1988
Richard Clarke, Deborah Kane, Carla Stewart Pathoming Organisation Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 D. Spentering Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 D. Supplementery Names Alantic City International Airport, NJ 08405 ACT-350 Abstract is study describes Fire Safety systems, cabin design and materials in cabin areas of tending and aircraft most commonly delivered. These aircraft represent 880 of 1100 nmuter aircraft and probably will be the majority of the commuter fleet in the future. The terials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the otreger eight aircraft, two are no longer delivered. Four newer and larger designs feature, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more comect, with interior storage limited to bins at the entry point. Thermoplastics and comestic materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushion the fire-blocking materials. Ston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other ght aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional xigen system using oxygen generators; the other aircraft use cylinder stored oxygen. The Aircraft Fires, Commuter Aircraft, and the other aircraft use cylinder stored oxygen.	CURRENI FIRE SAFETI D	resign aspects of commuter a	
Richard Clarke, Deborah Kane, Carla Stewart **Prisoning Organization Nume and Address** EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 **Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 **Actives** Is Supplementery Nates** **Actives** Is study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current per ation and aircraft most commonly delivered. These aircraft represent 880 of 1100 **mounter aircraft and probably will be the majority of the commuter fleet in the future.** **e trend in these commuter aircraft is increasing sophistication in application of terials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the ottrage eight aircraft, two are no longer delivered. Four newer and larger designs feature, separate baggage compartments. Only two aircraft have overhead storage bins. **e aircraft has a large interior with standing headroom. The others are much more comment, with interior storage limited to bins at the entry point. Thermoplastics and consiste materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic thire-blocking materials. **ston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other spit aircraft are turboprop aircraft using engine bleed air for cabin heating and cool: aircraft are turboprop aircraft using engine bleed air for cabin heating and cool: aircraft are turboprop aircraft using engine bleed air for cabin heating and cool: aircraft are unpressurized and four are pressurized. One new design has an optional vigen system using oxygen generators; the other aircraft use cylinder stored oxygen. Aircraft Fires, Commuter Aircraft, **There are unpressur	Author(s)		8. Performing Organization Report No.
EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124 2. Sensevine Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 3. Supplementary Neves 4. Abstract is study describes Fire Safety systems, cabin design and materials in cabin areas of to momon commuter aircraft. The aircraft were selected based upon a balance of current position and aircraft most commonly delivered. These aircraft represent 880 of 1100 mmuter aircraft and probably will be the majority of the commuter fleet in the future. The terrials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the other gight aircraft, two are no longer delivered. Four never and larger designs features, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more commercials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushift fire-blocking materials. The other aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional voyen system using oxygen generators; the other aircraft use cylinder stored oxygen. 7. Key Words Aircraft Fires, Commuter Aircraft, 10. Dismitules Steressen 10. Decument is available to the public through the National Technical Information.		rah Kane, Carla Stewart	
12.101 Toreador Lane Oakton, Virginia 22124 2. Sentising Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 3. Supplementary Name A. Abstract is study describes Fire Safety systems, cabin design and materials in cabin areas of to mimon commuter aircraft. The aircraft were selected based upon a balance of current potation and aircraft most commonly delivered. These aircraft represent 880 of 1100 mimuter aircraft and probably will be the majority of the commuter fleet in the future. The terrals similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the ofter eight aircraft, two are no longer delivered. Four newer and larger designs features, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more commenced the polyurethane cushions; currently, operators and manufacturers are protecting cushication powered aircraft use gasoline cabin heaters and ram cooling airflow. The other sight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft has an optional voyen system using oxygen generators; the other aircraft use cylinder stored oxygen. [18. Dismitusion of Authority and Police Covered FINAL REPORT 14. Sentising Agency Cede ACT-350 15. Supplementary Naive Action Commuter all Provided Covered FINAL REPORT 14. Sentising Agency Cede ACT-350 14. Sentising Agency Cede ACT-350 14. Sentising Agency Cede ACT-350 15. Supplementary Naive Action Commuter			10. Work Unit No. (TRAIS)
Oakton, Virginia 22124 2. Separating Agenty Home and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 3. Supplementary Notes 4. Abstract is study describes Fire Safety systems, cabin design and materials in cabin areas of to mmon commuter aircraft. The aircraft were selected based upon a balance of current potention at aircraft and probably will be the majority of the commuter fleet in the future. The aircraft is increasing sophistication in application of aterials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the other gree right aircraft, two are no longer delivered. Four newer and larger designs features, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more commenced, with interior storage limited to bins at the entry point. Thermoplastics and commence, with interior storage limited to bins at the entry point. Thermoplastics and commenced the polyurethane cushions; currently, operators and manufacturers are protecting cushic the fire-blocking materials. Aiston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other cight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are upressurized and four are pressurized. One new design has an optional ax aircraft are upressurized and four are pressurized. One new design has an optional ax aircraft are upressurized and four are pressurized. One new design has an optional frough the National Technical Information of the community and the national materials and content of the comm			1) Contract or Great Ma
U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 6. Abstreet in study describes Fire Safety systems, cabin design and materials in cabin areas of to momon commuter aircraft. The aircraft were selected based upon a balance of current position and aircraft most commonly delivered. These aircraft represent 880 of 1100 immuter aircraft and probably will be the majority of the commuter fleet in the future, are trend in these commuter aircraft is increasing sophistication in application of interials similar to those in large commercial aircraft. Among the ten aircraft two are deter, piston powered aircraft, simple in design and materials applications. Of the order gree eight aircraft, two are no longer delivered. Four newer and larger designs feature, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more composite materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic the fire-blocking materials. Liston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other light aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional count of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical Information of the commuter of the public through the National Technical I		.24	_
U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 6. Absired is study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current position and aircraft most commonly delivered. These aircraft represent 880 of 1100 mmuter aircraft and probably will be the majority of the commuter fleet in the future. The term of the commuter aircraft and aircraft is increasing sophistication in application of terrials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the other gree eight aircraft, two are no longer delivered. Four newer and larger designs features, separate baggage compartments. Only two aircraft have overhead storage bins. The moplastics and commonity, with interior storage limited to bins at the entry point. Thermoplastics and consiste materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic thire-blocking materials. International Aircraft use gasoline cabin heaters and ram cooling airflow. The other spit aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional country and available to the public through the National Technical Information Document is available to the public through the National Technical Information			<u> </u>
U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 3. Supplementary Nerves 4. Abstreet is study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current properties at the probably will be the majority of the commuter fleet in the future. The ternal in these commuter aircraft is increasing sophistication in application of atterials similar to those in large commercial aircraft. Among the ten aircraft two are der, piston powered aircraft, simple in design and materials applications. Of the other eight aircraft, two are no longer delivered. Four newer and larger designs features, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more consistent materials are used in the newer aircraft. Each aircraft originally was equipped the polyurethane cushions; currently, operators and manufacturers are protecting cushic the fire-blocking materials. Iston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft with other aircraft use cylinder stored oxygen. 7. Key Words Aircraft Fires, Commuter Aircraft, the other airc	2. Spansoring Agency Name and Add	Iress	
Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405 3. Supplementary Notes 4. Above: is study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current polation and aircraft most commonly delivered. These aircraft represent 880 of 1100 immuter aircraft and probably will be the majority of the commuter fleet in the future. The ternal in these commuter aircraft is increasing sophistication in application of aterials similar to those in large commercial aircraft. Among the ten aircraft two are lader, piston powered aircraft, simple in design and materials applications. Of the other arge eight aircraft, two are no longer delivered. Four newer and larger designs featurage, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more compact, with interior storage limited to bins at the entry point. Thermoplastics and composite materials are used in the newer aircraft. Each aircraft originally was equipped ith polyurethane cushions; currently, operators and manufacturers are protecting cushic ith fire-blocking materials. iston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other ight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling air aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are turboprop aircraft with the future. 17. Key Werds Aircraft Fir	U.S. Department of Ti	ransportation	Tana ital Orti
Atlantic City International Airport, NJ 08405 ACT-350 ACT-36 ACT-3	Federal Aviation Admi	inistration	14 Second Action Co. 15
16. Abstract This study describes Fire Safety systems, cabin design and materials in cabin areas of tommon commuter aircraft. The aircraft were selected based upon a balance of current polation and aircraft most commonly delivered. These aircraft represent 880 of 1100 commuter aircraft and probably will be the majority of the commuter fleet in the future. The trend in these commuter aircraft is increasing sophistication in application of aterials similar to those in large commercial aircraft. Among the ten aircraft two are lider, piston powered aircraft, simple in design and materials applications. Of the other arger eight aircraft, two are no longer delivered. Four newer and larger designs featuarge, separate baggage compartments. Only two aircraft have overhead storage bins. The aircraft has a large interior with standing headroom. The others are much more commact, with interior storage limited to bins at the entry point. Thermoplastics and composite materials are used in the newer aircraft. Each aircraft originally was equipped ith polyurethane cushions; currently, operators and manufacturers are protecting cushic ith fire-blocking materials. Iston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other ight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional xygen system using oxygen generators; the other aircraft use cylinder stored oxygen. 17. Key Verds Aircraft Fires, Commuter Aircraft, Abic Dismituted Stevensor	· · · · · · · · · · · · · · · · · · ·	ational Airnort NI 00/05	
arger eight aircraft, two are no longer delivered. Four newer and larger designs featuarge, separate baggage compartments. Only two aircraft have overhead storage bins. ne aircraft has a large interior with standing headroom. The others are much more comact, with interior storage limited to bins at the entry point. Thermoplastics and comosite materials are used in the newer aircraft. Each aircraft originally was equipped ith polyurethane cushions; currently, operators and manufacturers are protecting cushic ith fire-blocking materials. iston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other ight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional xygen system using oxygen generators; the other aircraft use cylinder stored oxygen. 17. Key Words Aircraft Fires, Commuter Aircraft, Document is available to the public through the National Technical Information	ommon commuter aircraft. lation and aircraft most	The aircraft were selecte commonly delivered. These	d based upon a balance of current pop aircraft represent 880 of 1100
act, with interior storage limited to bins at the entry point. Thermoplastics and composite materials are used in the newer aircraft. Each aircraft originally was equipped ith polyurethane cushions; currently, operators and manufacturers are protecting cushic ith fire-blocking materials. iston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other ight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling aircraft are unpressurized and four are pressurized. One new design has an optional xygen system using oxygen generators; the other aircraft use cylinder stored oxygen. 17. Key Words Aircraft Fires, Commuter Aircraft, Document is available to the public through the National Technical Information	ommon commuter aircraft. lation and aircraft most ommuter aircraft and prome trend in these commutaterials similar to thos	The aircraft were selecte commonly delivered. These bably will be the majority ter aircraft is increasing see in large commercial aircr	d based upon a balance of current pop aircraft represent 880 of 1100 of the commuter fleet in the future. ophistication in application of aft. Among the ten aircraft two are
ight aircraft are turboprop aircraft using engine bleed air for cabin heating and coordinative aircraft are unpressurized and four are pressurized. One new design has an optional exygen system using oxygen generators; the other aircraft use cylinder stored oxygen. 17. Key Words Aircraft Fires, Commuter Aircraft, Document is available to the public through the National Technical Information	ommon commuter aircraft. lation and aircraft most ommuter aircraft and protect the trend in these commutaterials similar to thos lder, piston powered air arger eight aircraft, two	The aircraft were selected commonly delivered. These shably will be the majority ser aircraft is increasing see in large commercial aircraft, simple in design and you are no longer delivered.	d based upon a balance of current pop aircraft represent 880 of 1100 of the commuter fleet in the future. ophistication in application of aft. Among the ten aircraft two are materials applications. Of the other Four newer and larger designs feature
Aircraft Fires, Commuter Aircraft, Document is available to the public through the National Technical Information	ommon commuter aircraft. lation and aircraft most ommuter aircraft and protection the trend in these commutaterials similar to thos lder, piston powered air arger eight aircraft, twarge, separate baggage cone aircraft has a large act, with interior storate osite materials are used ith polyurethane cushion	The aircraft were selected commonly delivered. These shably will be the majority ser aircraft is increasing see in large commercial aircraft, simple in design and so are no longer delivered. Compartments. Only two airces interior with standing heading limited to bins at the ell in the newer aircraft. East; currently, operators and	d based upon a balance of current pop aircraft represent 880 of 1100 of the commuter fleet in the future. ophistication in application of aft. Among the ten aircraft two are materials applications. Of the other Four newer and larger designs feature raft have overhead storage bins. Toom. The others are much more company point. Thermoplastics and company point. Thermoplastics and company point or aircraft originally was equipped
through the National Technical Information	ommon commuter aircraft. Lation and aircraft most ommuter aircraft and prometer trend in these commutaterials similar to those lder, piston powered aircraft, twarge, separate baggage of the aircraft has a large act, with interior storal posite materials are used ith polyurethane cushion ith fire-blocking materials are turbog is aircraft are turbog in aircraft are unpression and aircraft are turbog is aircraft are unpression.	The aircraft were selected commonly delivered. These shably will be the majority ser aircraft is increasing see in large commercial aircraft, simple in design and so are no longer delivered. Compartments. Only two airces interior with standing heading limited to bins at the ellin the newer aircraft. Easis; currently, operators and eals. Use gasoline cabin heaters a prop aircraft using engine burized and four are pressuri	d based upon a balance of current pop aircraft represent 880 of 1100 of the commuter fleet in the future. ophistication in application of aft. Among the ten aircraft two are materials applications. Of the other four newer and larger designs featur raft have overhead storage bins. Toom. The others are much more commentry point. Thermoplastics and commentry point of aircraft originally was equipped manufacturers are protecting cushion and ram cooling airflow. The other sleed air for cabin heating and cooling airflow. One new design has an optional
	ommon commuter aircraft. Lation and aircraft most ommuter aircraft and prome trend in these commutatorials similar to those der, piston powered aircraft, twarge, separate baggage of the aircraft has a large act, with interior storations to materials are used ith polyurethane cushion ith fire-blocking materials that aircraft are turbound it aircraft are turbound aircraft are unpressury system using oxygen system using oxygen.	The aircraft were selected commonly delivered. These shably will be the majority ser aircraft is increasing see in large commercial aircraft, simple in design and so are no longer delivered. Compartments. Only two airces interior with standing heading limited to bins at the ellin the newer aircraft. Easts; currently, operators and easts. The aircraft using engine burized and four are pressuring engenerators; the other aircraft is compartments.	d based upon a balance of current por aircraft represent 880 of 1100 of the commuter fleet in the future. ophistication in application of aft. Among the ten aircraft two are materials applications. Of the other four newer and larger designs feature raft have overhead storage bins. Toom. The others are much more commentry point. Thermoplastics and commentry point. Thermoplastics and commentary are protecting cushion and ram cooling airflow. The other sleed air for cabin heating and cooling airflow. One new design has an optional excraft use cylinder stored oxygen.

Form DOT F 1700.7 (8-72)

Unclassified

19. Security Classif. (of this report)

20, Security Cleasif, (of this page)

Unclassified

21. No. of Pages

76

22. Price

PREFACE

This report was prepared by EVENTS ANALYSIS. Inc. under Contract No. DTFA03-86-C-00062 with the Federal Aviation Administration (FAA) Technical Center, where Gerald R. Slusher acted as Technical Monitor.

The EVENTS ANALYSIS. Inc. Program Manager has been Richard W. Clarke. with subcontract assistance by Phaneuf Associates Incorporated and by Veda Incorporated. The Phaneuf Associates subcontract manager has been Dr. Roger Phaneuf; Veda Incorporated's subcontract manager has been Mr. Ron Bentley. The following persons and organizations have been of noteworthy help in compiling information used during this study:

Mssrs. John Thompson and Dennis Lints. The deHavilland Aircraft Company of Canada

Mr. Charles Benn, owner/operator of the recently closed Woodbridge Airport, Virginia

Mr. Alan A. Driver, British Aerospace, Inc.

Mr. Raymond R. Gould, British Aerospace, Inc.

Ms. Teresa Allegri, Jetstream International Airlines

Mr. Tom Peay, Colgan Airways Corporation

Ms. Rebecca Garner, Cessna Aircraft

Mr. Bernard Castell, Embraer Aircraft

Mr. Tom Peck, Embraer Aircraft

Mr. Ken Morgan, Embraer Aircraft

Mr. Michael Gibson, Atlantic Southeast Airlines

Mr. Ray Crist, Piper Aircraft

Mr. Maurice Panther, Short Brothers (U.S.A.) Inc.

Mr. David Fox, Short Brothers, PLC

Mr. Jeff Robinson, Henson Airlines

Mr. Jim Cupp, Fairchild Aircraft Corporation

Mr. Curt Ward, Comair

Accesion For	<u> </u>
NTIS CRA&I DFIC TAB Unanno ir zed Justifization	in D
By Distribution /	
Availability	Chars
Dist Avait an Speci	
A-1	

TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	ix
INTRODUCTION	1
Purpose	1
Background	1
THE POPULATION OF COMMUTER AIRCRAFT	2
Purpose	2
Approach	2
Population Research	2
Population Definition	3
COMMUTER AIRCRAFT MATERIALS AND SYSTEMS RESEARCH	7
Purpose	7
Methodology	7
Organization	7
COMPARTMENTATION	8
Baggage Areas	8
Stowage Compartments	21
Lavatories	21
Galleys	22 23
Firewalls	23
Partitions	23
MATERIALS	25
Lining Materials	25
Floor Coverings	29
Major Transparencies	30
Seats	31
Insulation	32 32
Wire Insulation	34
Fuselage Skin Thickness	34

SYSTEMS	45
Fire Detection Fire Suppression	45 46
Hand Extinguishers Oxygen Systems Ventilation Systems	47 48 63
SUMMARY	75

Son seeds 's seeds

APPENDIX - DISTRIBUTION LIST

LIST OF FIGURES

rigu	ce ce	Page
1.	Illustrations of the Ten Selected Commuter Aircraft. (2 pages)	5
2.	BAe Jetstream 3100 Compartmentation.	11
3.	Beech 99 Airliner Compartmentation.	12
4.	Beech 1900 Airliner Compartmentation.	13
5.	Cessna 402 Compartmentation.	14
6.	Twin Otter Series 300 Compartmentation.	15
7.	Embraer Bandeirante Compartmentation.	16
8.	Embraer Brasilia Compartmentation.	17
9.	Fairchild Metro III Compartmentation.	18
10.	Piper Navajo Compartmentation.	19
11.	Shorts 3-30 Compartmentation.	20
12.	BAe Jetstream 3100 Airliner Fuselage Skin Thickness.	35
13.	Beech 99 Airliner Fuselage Skin Thickness.	36
14.	Beech 1900 Airliner Fuselage Skin Thickness.	37
15.	Cessna 402 Fuselage Skin Thickness.	38
16.	Twin Otter Series 300 Fuselage Skin Thickness.	39
17.	Embraer Bandeirante Fuselage Skin Thickness	40
18.	Embraer Brasilia Fuselage Skin Thickness	41
19.	Fairchild Metro III Fuselage Skin Thickness	42
20.	Piper Navajo Fuselage Skin Thickness.	43
21.	Shorts 3-30 Fuselage Skin Thickness.	44
22.	BAe Jetstream 3100 Fire Detection, Fire Suppression, and Oxygen Systems.	51
23.	Beech 99 Fire Detection. Fire Suppression. and Oxygen Systems.	52
24.	Beech 1900 Airliner Fire Detection and Suppression Systems.	53
25.	Reach 1900 Airliner Overen Systems	54

1	26.	Cessna 402 Fire Detection, Fire Suppression, and Oxygen Systems.	55	× ×
	27.	Twin Otter Series 300 Fire Detection, Fire Suppression, and Oxygen Systems.	56	X
	28.	Embraer Bandeirante Fire Detection, Fire Suppression, and Oxygen Systems	57	XXXXX DXXXXI DXXXX
	29.	Embraer Brasilia Fire Detection. Fire Suppression. and Oxygen Systems.	58	28.27
	30.	Fairchild Metro III Fire Detection, Fire Suppression, and Oxygen Systems.	59	338
-	31.	Turbine powered Navajo Chieftain Fire Detection and Fire Suppression Systems.	60	
Š	32.	Piper Navajo Oxygen System.	61	
<u>소</u>	33.	Shorts 3-30 Fire Detection, Fire Suppression, and Oxygen Systems.	62	1
\$ \$	34.	BAe Jetstream 3100 Ventilation System.	65	
8	35.	Beech 99 Airliner Ventilation System.	66	. 1522252
.	36.	Beech 1900 Airliner Ventilation.	67	
	37.	Cessna 402 Ventilation.	68	3
	38.	Twin Otter Series 300 Ventilation System.	69	**************************************
8	39.	Embraer Bandeirante Ventilation System.	70	
	40.	Embraer Brasilia Ventilation System.	71	(1188818)
	41.	Fairchild Metro III Ventilation System.	72	8
	42.	Piper Navajo Ventilation System.	73	3
**************************************	43.	Shorts 3-30 Ventilation System.	74	22223
Ž.				3
88				KOZOGO
				Q
PXXXXXX				<u> </u>
ķ.		vii		3
×				77.2
120000000000	**************************************	<u>ŢŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖŖ</u>	<u> </u>	4.555550

LIST OF TABLES

Tab.	16	Page
1.	The Ten Most Common Commuter Aircraft based on FAA Census of Civil Aircraft 1984.	2
2.	The Ten Most Common Commuter Aircraft based on Regional Airline Association and FAA Data 1986.	3
3.	World Aviation Directory Totals of Commuter Aircraft Deliveries for 1984, 1985 and January-October 1986.	3
4.	Alphabetical List of the Ten Commuter Aircraft Selected for Inclusion in the FAA Commuter Aircraft Fire Study.	4
5.	Commuter Aircraft Baggage Areas.	9
6.	Commuter Aircraft Stowage Compartments.	21
7.	Commuter Aircraft Lavatory Areas.	22
8.	Commuter Aircraft Galley Areas.	23
9.	Commuter Aircraft Fuselage Area Partitions.	24
10.	Commuter Aircraft Cabin Lining Materials.	26
11.	Commuter Aircraft Baggage Area Lining Materials.	28
12.	Commuter Aircraft Floor Coverings.	29
13.	Commuter Aircraft Transparency Materials.	30
14.	Commuter Aircraft Seat Materials.	31
15.	Commuter Aircraft Fuselage Insulation.	32
16.	Commuter Aircraft Wiring Insulation.	33
17.	Commuter Aircraft Fire Detection Systems.	45
18.	Commuter Aircraft Fire Suppression Systems.	46
19.	Commuter Aircraft Hand Fire Extinguishers.	47
20.	Commuter Aircraft Oxygen Systems.	49
21.	Commuter Aircraft Ventilation Systems.	63

EXECUTIVE SUMMARY

This study describes fire safety systems and airframe design as well as applications of construction materials in cabin areas of ten common commuter class aircraft. The ten commuter aircraft have been selected to represent those aircraft most common in the commuter fleet. The aircraft in this study represent the majority of the current regional airline fleet of aircraft carrying thirty or fewer passenger, and, due to their numbers in service (880 out of 1100 commuter class aircraft), will remain representative of the population for several more years. The trend in the design of commuter airliners, as seen in this study, is that of increasing sophistication in application of materials similar to those found in large commercial aircraft. With the exception of two aircraft, the commuter aircraft are small and offer relatively high performance.

The aircraft in this study illustrate trends in the commuter aircraft industry. The only two piston powered aircraft originated as general aviation aircraft designs some years ago. They are relatively small and simple in both design and materials applications. Of the other and larger eight aircraft, two are at the end of their delivery periods. These are a derivative of aircraft which were adapted to commuter service. One other aircraft, while a relatively new design, is not being delivered currently due to market desire for larger aircraft.

Of the eight larger aircraft, application of modern, composite materials is a major characteristic of the aircraft. Four of the newer and larger designs feature large, rear located, separate baggage compartments, leaving the cabin for seating. Only in two are overhead storage bins found.

AND THE PROPERTY OF THE PROPER

Of the ten aircraft, one has a large interior that allows standing headroom in its large interior volume. The other aircraft are much more compact, with interior storage limited to bins at the entry end of the aircraft. Weight saving seems to be key to design success, possibly affecting the selection of various new thermoplastics and composite materials for the interiors. Each aircraft was originally delivered with polyurethane cushions; currently operators and manufacturers are involved in covering these cushions with fire blocking materials to upgrade fire safety.

COMMINICACION A 12 CACAGAGA INSTANTA CACAGAGA DE CACAGAGA A CONTRA DE CONTRA DE CONTRA DE CONTRA DE CONTRA DE C

The two piston powered aircraft use gasoline fired heaters to provide cabin heat and ram air flow to provide outside air for cabin and cockpit cooling; these heaters are not equipped with fire detection or extinguishing systems. The remainder of the aircraft are turbine powered, turboprop aircraft that use engine bleed air for heating and cooling of the interior air. Six of the aircraft are unpressurized aircraft while four are of pressurized design. unpressurized aircraft have oxygen available for the pilots and passengers. often in portable storage form. The pressurized aircraft feature cabin oxygen for the passengers. Each of these aircraft reflect their operating environment of short, low altitude flight legs, not requiring design of oxygen systems characteristic of large commercial aircraft. In some of the aircraft, the fixed oxygen system is an option picked only by operators faced with the need for sustained high altitude operations, such as in mountainous areas. In these aircraft, oxygen is meant for emergency use of the crew and individual passengers with a temporary need.

INTRODUCTION

PURPOSE.

The purpose of this study was to achieve an understanding of the basic fire safety related design and materials application characteristics of aircraft commonly found in the U.S. commuter aircraft fleet. The goals of the study were to:

- Survey the makeup of the commuter fleet to identify ten aircraft that are both common and typical of the commuter aircraft in use.
- For those ten aircraft, identify the materials used in the cabins of the aircraft.
- For those ten aircraft, identify and describe the compartmentation and materials used in partitioning the aircraft.
- For those ten aircraft, identify and describe fire detection and suppression, oxygen, ventilation systems and hand held fire extinguishers.

BACKGROUND.

and have a some a some a market a posterior of the source of the source

Since enactment of the Airline Deregulation Act of 1978 there have been major changes in the character of U.S. commercial aviation. Scheduled air carriers have concentrated their resources to meet new competition by forming "hub and spoke" route systems. With major airlines concentrating on larger cities. small towns and cities suffered a loss of air service. In an attempt to meet this need, both existing and new commuter airlines entered the vacated markets and expanded service to other communities not previously served.

In this way a formerly small and ill defined part of the air transportation system changed into a major aviation activity --- commuter or regional Starting with small aircraft that were originally general aviation airlines. in origin and with older aircraft at the low end of the transport aircraft spectrum, the commuter carriers struggled through several years of economic hardship to establish visibility and credibility in the eyes of the traveling One of the problems faced by commuter carriers was the lack of public. economic aircraft to meet the rapidly expanding service needs. modern, the early 1980s, aircraft and engine manufacturers began to market new aircraft that were modern in design, powered by turboprop engines and carrying up to thirty passengers. Those aircraft, many manufactured overseas, are now becoming a common sight at U.S. airports. The newly created U.S. commuter fleet is now in service and, due to its rapid growth focused in the 1980s. will retain its basic characteristics for many years to come.

Federal Aviation Administration (FAA) aircraft fire safety programs have been primarily devoted to transport category aircraft. A large body of knowledge and experience had been amassed on these aircraft. Today, with the new commuter aircraft in service, no comparable body of information exists for those new commuter aircraft. For this reason, the FAA's Technical Center's (FAATC) Fire Safety Branch initiated this study to document the fire safety design characteristics of the commuter fleet to establish what sort of

research might be necessary in the future and how much of the existing data on aircraft construction and materials carries over to the new commuter aircraft fleet. Since these aircraft have only come into use in the last few years, there is no body of accident experience that is pertinent. Instead the opportunity existed to review the new fleet's characteristics and establish an information base to which future experience could be compared.

THE POPULATION OF COMMUTER AIRCRAFT

PURPOSE.

The first objective of the current Fire Safety Design Aspects of Commuter Aircraft was to develop a list of aircraft for which fire safety design details would be determined. For this stage of the project. commuter class aircraft with passenger capacity of thirty or fewer passengers were reviewed and ten were selected for further study.

APPROACH.

Two separate approaches were used to obtain the final list of commuter aircraft. The first approach was to identify the ten most populous commuter aircraft used in the U.S. while the second approach was to identify the six commuter aircraft being sold or delivered at the highest rates during the most recent two years. From these two lists, a combined list balancing past production against future deliveries was developed.

POPULATION RESEARCH.

According to the FAA's Census of U.S. Civil Aircraft for 1984, the ten most common commuter aircraft were the following.

TABLE 1. THE TEN MOST COMMON COMMUTER AIRCRAFT BASED ON FAA CENSUS OF CIVIL AIRCRAFT - 1984.

Number
107
9 9
97
97
79
70
68
27
27
17

A second list of ten was developed from two other sources, the Regional Airline Association's (RAA) 1986 Annual Report of the Regional/Commuter Airline Industry and the FAA's Aircraft Utilization & Propulsion Reliability Report for May and June, 1986. In comparing these two sources, it was noted that the totals for the different aircraft types varied, yet the top ten commuter aircraft were nearly the same in each source. Balancing the varying

totals on the ten most common aircraft in these sources, the following fleet total was developed.

TABLE 2. THE TEN MOST COMMON COMMUTER AIRCRAFT BASED ON REGIONAL AIRLINE ASSOCIATION AND FAA DATA - 1986.

Туре	Number
Cessna 402	190
Piper Navajo PA-31	109
Beech 99	106
deHavilland Twin Otter DHC-6	106
Fairchild Metro II SA-226	103
Fairchild Metro III SA-227	97
Embraer Bandeirante EMB-110	86
British Aerospace BAe Jetstream 3100	83
Beech 1900	47
Shorts 330 SD 3-30	41

TANKSON DEFECTED FORSKON BESSESSEE

The <u>World Aviation Directory</u> tabulation of "Business/Personal Aircraft Unit Shipments" for calendar years 1984. 1985 and for the period January-October. 1986 was used to identify the commuter aircraft being sold or delivered at the highest rate during the most recent two years.

TABLE 3. WORLD AVIATION DIRECTORY TOTALS OF COMMUTER AIRCRAFT DELIVERIES FOR 1984, 1985 AND JANUARY-OCTOBER 1986.

Туре	1984 Total	1985 Total	1986 Total	
BAe Jetstream 3100	22	34	36	
Beech 1900	29	21	13	
Cessna 402	11	14	1	
deHavilland DHC-6	14	18	2	
Embraer EMB-110	9	8	5	
Embraer EMB-120	-	6	10	
Fairchild SA-227	23	20	23	
Pilatus BN-2	5	2	6	

Eight, rather than the required six aircraft, were reported since these eight were the only commuter aircraft being delivered in significant numbers in the 1985-1986 period.

POPULATION DEFINITION.


The lists shown in tables 2 and 3 were provided for consideration and compilation into a composite list reflecting both existing commuter aircraft and those likely to be most common in the future due to delivery trends. Such a list was determined after consultation with FAA Central Region representatives responsible for commuter aircraft certification. The final list of ten aircraft for further study was selected from the candidate aircraft and is as follows:

TABLE 4. ALPHABETICAL LIST OF THE TEN COMMUTER AIRCRAFT SELECTED FOR INCLUSION IN THE FAA COMMUTER AIRCRAFT FIRE STUDY.

British Aerospace BAe Jetstream 3100 Beech 99 (BE-99) Beech 1900 (BE-1900) Cessna 402 (CE-402) deHavilland Twin Otter (DHC-6) Embraer Bandeirante (EMB-110) Embraer Brasilia (EMB-120) Fairchild Metro III (SA-227) Piper Navajo (PA-31) Shorts 330 (SD 3-30)

These ten aircraft, in the summer of 1986 represented an approximate total of 880 of the nearly 1100 commuter aircraft counted by the FAA as being in the U.S. commuter aircraft fleet. From this it can be seen that the ten aircraft are representative of the present fleet and likely will remain so for some time to come.


The section of the se




BAe JETSTREAM 3100 19 PASSENGERS




BEECH 99 15 PASSENGERS



BEECH 1900 15 PASSENGERS



CESSNA 402 8 PASSENGERS




TWIN OTTER SERIES 300 20 PASSENGERS




EMBRAER BANDEIRANTE
19 PASSENGERS


FIGURE 1. ILLUSTRATIONS OF THE TEN SELECTED COMMUTER AIRCRAFT (1 of 2 pages)



EMBRAER BRASILIA 30 PASSENGERS



FAIRCHILD METRO III
19 PASSENGERS



PIPER NAVAJO 9 PASSENGERS



SHORTS 330 30 PASSENGERS

FIGURE 1. ILLUSTRATIONS OF THE TEN SELECTED COMMUTER AIRCRAFT (2 OF 2 PAGES)

COMMUTER AIRCRAFT MATERIALS AND SYSTEMS RESEARCH

PURPOSE.

The intent of the Current Fire Safety Design Aspects of Commuter Aircraft was to document the fire safety provisions and design elements of the ten selected This documentation focused on three general areas of aircraft design and construction: cabin materials, aircraft compartmentation and fire related systems. For cabin materials, the study covered: cabin and baggage area liners, floor coverings, major transparencies, seats, insulation, cabin area fuselage skin thickness, and flight deck and cabin area wire insulation. For aircraft compartmentation the intent was to portray baggage area location and accessibility, lavatory location and materials of construction, location and materials of construction, cabin firewalls and materials of construction, flight deck firewalls and materials of construction, partitions and their composition, and stowage compartments and their composition. fire related systems this study describes fire detection and suppression on-board hand held fire extinguishers, oxygen ventilation systems. Both text and illustrations are used in explaining these systems' details.

METHODOLOGY.

Personal Property

For each aircraft a two-fold approach was taken in obtaining the necessary Each manufacturer was contacted regarding the information information. At the same time, operators of the ten selected aircraft were requirements. Based upon conversations with contacted to obtain similar information. ranufacturers and operators, representative aircraft configurations were This was due to the variety of configuration options that were selected. available in several of the aircraft. The configuration selected for the study was felt to be the most likely to be encountered or the most common in the fleet, for that aircraft. As an example, though most of the aircraft could be equipped with a galley, galleys were not generally an option selected by operators faced with the need to maximize revenue producing load over often short flight distances and times.

ORGANIZATION.

The data developed in this investigation are organized on a topic basis rather than a model basis. Much of the information is presented through illustrations. Aircraft compartmentation is described in illustrated format in figures 2 through 11. Amplification of some details of compartmentation is offered by text descriptions.

Materials applications, except for fuselage skin thickness, are described in text form with each aircraft being summarized under separate material application, e.g., cabin and baggage area liners are described for each of the ten aircraft, followed by descriptions of floor coverings for each of the ten aircraft. Cabin area fuselage thickness for each of the ten aircraft is described in pictorial form in figures 12 through 21.

Aircraft fire related systems are described using both illustrations and text. Figures 22 through 43 illustrate layout of fire detection and suppression systems, oxygen systems and ventilation systems. This information is supplemented by text descriptions of design specifications and other details.

COMPARTMENTATION

BAGGAGE AREAS.

For purposes of describing the fireworthiness capabilities of cargo or baggage compartments, transport category aircraft cargo/baggage compartments are described by five classes of fireworthiness. Each is typified by differing characteristics of accessibility, ventilation, fire or smoke detection, fire extinguishing, and volume. These classifications are listed in Federal Aviation Regulations Part 25.857 - Cargo Compartment Classification. Though several of the aircraft surveyed for this report were not designed according to the standards of Part 25, which applies to transport category aircraft rather than commuter aircraft, several of the manufacturers have described the fire worthiness characteristics of their aircraft's baggage compartments in terms of the Part 25 classification. The five classes of baggage compartment are summarized, below:

- Class A A compartment in which the presence of fire would be easily discovered while a crewmember is at his or her station and the compartment is easily accessible, in flight.
- Class B A compartment in which there is sufficient access, in flight, to enable a crewmember to effectively reach the entire contents of the compartment with a hand fire extinguisher. Further, when the crewmember is accessing the compartment, no hazardous quantity of smoke, flames, or fire extinguishing agent will enter any compartment occupied by crew or passengers. For this Class of compartment there must be a separate, approved smoke or fire detector at the pilot's or flight engineer's station.
- Class C A compartment not meeting the requirements of either Class A or B. but which has a separate, approved fire or smoke detector at the pilot's or flight engineer's station. Class C compartments will have an approved, built in fire extinguishing system controlled at the pilot's or flight engineer's station. Like the Class B compartment, the Class C compartment must have means to prevent hazardous quantities of smoke, flames, or fire extinguishing agent from entering any compartment occupied by crew or passengers. In addition to these requirements, the Class C compartment will have means to control ventilation and drafts within the compartment so that the fire extinguishing agent can control any fire that may start within the compartment.
- Class D These are compartments in which a fire occurring in the compartment will be completely confined without endangering the safety of the airplane or the occupants. For Class D compartments there will be means of preventing hazardous quantities of smoke, flames, or fire extinguishing agent from entering any compartment occupied by crew or passengers, and both ventilation and drafts will be controlled

<u>ᡏݤᡧᡗᠵᠸᠵᢞᡘᢣᢗᠵᡧᡗᡮᡗᡧᡗᠵᡧᡗᡛᠫᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡗᡮᡘᢜᡘᡮᡭᠸᡭᡳᡭᢗᡭᢗᠪᠪᡐᡗᡐᡐᡐᡗᡤᡘᠪᡐᡗᡏᡘᢉᠲᡗᠪᡭᡏᡭᠪᡗᢥ</u>ᡏ

so any fire within the compartment will not progress beyond same limits. For Class D compartments consideration will be given to the effect of heat within the compartment on adjacent critical parts of the airplane. For compartments of 500 cubic feet or less volume, an airflow of 1500 cubic feet per hour is acceptable. The volume of a Class D compartment will not exceed 1,000 cubic feet.

8333. Saaraa Reessa Reessa

22222

Class E - These compartments are used only for the carriage of cargo and must have a separate, approved smoke or fire detection system at the pilot's or flight engineer's station. For these compartments there will be means to shut off ventilation airflow to or within the compartment, and the controls for these means will be accessible to the flight crew in the crew compartment. There will be means to prevent hazardous quantities of smoke, flames, or fire extinguishing agent from entering the flight crew compartment; and required crew emergency exits will be accessible under any cargo loading condition.

Of the ten aircraft, eight used the fuselage area for baggage storage, usually in baggage compartments behind the cabin, and often in smaller compartments forward of the cockpit. In the Cessna 402, Jetstream 3100, Fairchild Metro III, Beech 99, and Piper Navajo, the fuselage baggage area is at the rear of the passenger cabin and is open to the cabin area. Only the Beech 99 series of aircraft featured use of an external belly pod for additional baggage. In the two smallest aircraft, the Cessna 402 and the Piper Navajo, baggage stowage is also possible in enclosed lockers at the top, rear of each of the engine nacelles. This nacelle location is a reflection of the origin of those two aircraft as general aviation aircraft. Figures 2 through 11 illustrate the location of the baggage areas as part of aircraft compartmentation.

TABLE 5. COMMUTER AIRCKAFT BAGGAGE AREAS

ROSSON REPORTED REPOR

Aircraft Type	Descriptions
BAe Jetstream 3100	Open bin storage at the rear end of the cabin area. (96.7 cubic feet) open and accessible from inside the cabin.
Beech 99	Baggage areas forward of the cockpit (43.9 cubic feet) and behind the cabin (17.1 cubic feet), with the nose baggage not accessible in flight. Rear baggage compartment separated from cabin by webbing. Some aircraft equipped with a fiberglass belly pod (59.4 cubic feet) accessible only from outside.
Beech 1900	Baggage areas forward of the cockpit (13 cubic feet) and behind the cabin (154 cubic feet), neither accessible in flight. Additional baggage in a storage bin at the forward right of the cabin (15 cubic feet) opposite the entry door.

Cessna 402

Baggage areas forward of the cockpit (26 cubic feet), in the top rear section of each engine nacelle (8.9 cubic feet each), and behind the cabin (31.7 cubic feet). The nose and the nacelle baggage compartments are not accessible in flight. The rear baggage compartment is an open bin aft of the entry doorway in the rear of the cabin.

deHavilland Twin Otter

Baggage areas forward of the cockpit (38 cubic feet) and behind the cabin (88 cubic feet). The forward area (Class D) is not accessible in flight, while the rear baggage compartment (Class B) can be accessed through a hatch at the top center of the aft bulkhead of the passenger cabin.

Embraer Bandeirante

Single baggage bin (113 cubic feet) at the rear of the cabin, separated from the cabin by a folding vinyl divider.

Embraer Brasilia

Single Class D baggage compartment (226 cubic feet) behind the rear cabin partition and not accessible in flight.

Fairchild Metro III


Baggage areas forward of the cockpit (45 cubic feet) and behind the rear cabin bulkhead (136 cubic feet). neither accessible in flight. Open baggage bin at the right front of the passenger cabin.

Piper Navajo

Baggage areas forward of the cockpit (14 cubic feet) and in the top rear of each engine nacelle (13.25 cubic feet each), neither accessible in flight. Open baggage area at the rear of the cabin accessible in flight (22 cubic feet).

Shorts 330

Baggage areas forward of the cockpit (45 cubic feet) and behind the cabin (170 cubic feet), neither accessible in flight.



TANKS OF THE PROPERTY OF THE P

FIGURE 2. BAE JETSTREAM 3100 COMPARTMENTATION

CONTILL SOCIETY FLOODIN FREEDRY FENERAL MONTHS BOOMING DISCUSSE STATES




FIGURE 3. BEECH 99 AIRLINER COMPARTMENTATION




FIGURE 4. BEECH 1900 AIRLINER COMPARTMENTATION

CONTROL SOCIONAL PROPERTY PRODUCES PURSONS

STATES OF THE PERSONS





FIGURE 5. CESSNA 402 COMPARTMENTATION

* SOCIONE MICHIEL MICHIEL BETWEEN BESTER BETWEEN BETWEEN BETWEEN WARREN BETWEEN BETWEE








FIGURE 7. EMBRAER BANDEIRANTE COMPARTMENTATION

AND CREEKS . WASH, STAND WASH, WASH, WASH, WASH, WASH, WASH, WASH, WASH, WASH



EMBRAER BRASILIA COMPARTMENTATION ထ FIGURE

POSTORIA LABORAN XXXXXXII DINAMINI BERNOTA DINAMINI DINAM



ACCOMPANIENT CONTRACTOR OF THE PROPERTY OF THE

FIGURE 9. FAIRCHILD METRO III COMPARTMENTATION

WWW. WENN WENN DENNY WENNY WOODS BOOKS WINNE WOODS

FIGURE 10. PIPER NAVAJO COMPARTMENTATION




FIGURE 11. SHORTS 3-30 COMPARTMENTATION

han bacca becar becar becard bacca bacca.

STOWAGE COMPARTMENTS.

Due to the size of most of the ten aircraft, stowage compartments are not common. In the larger aircraft, the Brasilia and Shorts 330, overhead bins are found in the cabin. In the Jetstream 3100 and the Fairchild Metro III, there are bin areas at one end of the cabin near the entry doorway.

TABLE 6. COMMUTER AIRCRAFT STOWAGE COMPARTMENTS

Aircraft Type Descriptions

BAe Jetstream 3100 Stowage compartments at the right rear of the cabin

opposite the entry doorway.

Beech 99 None.

Beech 1900 None.

Cessna 402 None.

deHavilland Twin Otter None.

Embraer Bandeirante None.

Embraer Brasilia Overhead bins in the cabin only along the right side

of the cabin. above the double row of seats. Total

volume of 32.1 cubic feet.

Fairchild Metro III Baggage area/closet at the right forward end of the

cabin opposite the doorway.

Piper Navajo None.

Shorts 330 Overhead storage bins on each side of the cabin above

the seats.

LAVATORIES.

<u> 1990-ben a decembração a possibila a laboração a finadación a laboração de labora</u>

Only in the two larger aircraft, the Brasilia and the Shorts 330, are lavatories to be found. The other eight aircraft cabins are configured only for passenger and crew seating.

TABLE 7. COMMUTER AIRCRAFT LAVATORY AREAS

Aircraft Type Descriptions

BAe Jetstream 3100 None.

Beech 99 None.

Beech 1900 None.

Cessna 402 None.

deHavilland Twin Otter None.

Embraer Bandeirante None.

Embraer Brasilia Optionally available and installed in either the

right forward or right rear part of the cabin area. Constructed of composite material lined with vinyl. Lavatory over a stainless steel pan, in turn, mounted

to the honeycomb cabin floor structure.

Fairchild Metro III None.

Piper Navajo None.

Shorts 330 Located

Located in the rear of the cabin area. Compartment panels of vacuum oven cure honeycomb sandwich panel 1/4 inch thick with 1/8 inch cell 1.5 lb./cubic foot Nomex* honeycomb. Facings a single 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.006 inch vinyl faced with 0.001 inch polyvinyl fluoride (PVF) (Schneller Aerfilm). Mouldings and trim pieces are vacuum oven cured multi laminate of phenolic resin pre-impregnated glass (various thicknesses 0.02-0.06 cloth inches). Visible surfaces painted with water base aircraft interior quality emulsion paint. Lavatory door a vacuum oven cure honeycomb sandwich panel with a 3/4 inch thick. 1/8 inch cell. 1.5 lb./cubic foot Nomex honeycomb core. Facing of two 0.1mm laminates of phenolic resin pre-impregnated glass cloth on each Decor of both sides covered with 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm).

GALLEYS.

As for lavatories, in the study group of aircraft, only the two largest aircraft, the Brasilia and Shorts 330, feature a galley area. This galley is typically small and suited for simple cabin service such as beverages.

* Nomex is a registered trademark for DuPont.

<u>የዕራንኤተርኤተርቀርናር የኤትርክርክርስ የራይር የ</u>ተርፈርትር የኤትርክርስ የሚያርፈርት የኤትርክርስ የኤትርስ የኤትርስ የኤትርክርስ የኤትርክርስ የኤትርክርስ የኤትርክርስ የኤትርክርስ የኤትርክርስ የኤትርክርስ የ

TABLE 8. COMMUTER AIRCRAFT GALLEY AREAS

Aircraft Type

Descriptions

BAe Jetstream 3100

None.

Beech 99

None.

Beech 1900

None.

Cessna 402

None.

deHavilland Twin Otter

None.

Embraer Bandeirante

None.

Embraer Brasilia

Optionally installed at the left or right rear of the cabin or just aft of the cabin entry doorway on the

POCOCOCO PACCOCOCO

Received

10000000 AUGUST

50000000

left side.

Fairchild Metro III

None.

Piper Navajo

None.

Shorts 330

Located at the rear of the cabin. Locker doors are of vacuum oven cure honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Door facings are one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each Door decor is 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm). Galley Locker and caps are vacuum oven cured multi-lamimate of phenolic resin impregnated glass cloth of various thickness (0.02-0.06 inch). Visible surfaces painted with water base aircraft interior quality emulsion Locker top panels are vacuum oven cure honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Panel facings are one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Panel decor is 0.001 inch PVF film (Tedlar).

FIREWALLS.

Manufacturers of the commuter aircraft surveyed report none of the aircraft have firewalls incorporated in the design of the cabin/fuselage area.

PARTITIONS.

In the ten aircraft, wood core sandwich panels are common, usually faced with aluminum or fiberglass. In the two newer design aircraft, the Brasilia and the Shorts 330, various combinations of thermoplastic are common. In the case of the Brasilia, newer materials were applied to the aircraft to achieve significant weight reductions.

TABLE 9. COMMUTER AIRCRAFT FUSELAGE AREA PARTITIONS

INDLE 9. C	OMMUTER AIRCRAFT FUSELAGE AREA PARTITIONS
Aircraft Type	Descriptions
BAe Jetstream 3100	Partition at the forward edge of the main entry door between the cockpit and cabin constructed of honeycomb laminate. Construction of 0.78 inch Fiberlam (0.75 inch Nomex with epoxy skins of 0.015 inches) and of 0.28 inch Fiberlam (0.25 inch Nomex with epoxy skin of 0.015 inches).
Beech 99	No partitions. Sliding curtain separates pilots and the cabin, curtain fabric matching seat material such as vinyl or wool fabric.
Beech 1900	Sliding door partition separates pilots from cabin. and a partition with hinged top half separates the cabin from the rear baggage area. Partitions constructed of 1 inch aluminum honeycomb and veneer.
Cessna 402	Single partition at the rear of the cabin, separating the cabin and the tail cone area. The partition of plywood construction covered with high pressure laminate.
deHavilland Twin Otter	Forward partition between cabin and cockpit of 0.50 inch plywood core with formica (phenolic) facing. Sliding door in partition of 0.50 inch balsa wood core with formica facing. Rear bulkhead between cabin and baggage compartment of 0.020 inch aluminum and 0.032 inch Acrylic/PVC (Kydex) thermoplastic with naugahyde fabric covering and of 0.032 inch Acrylic/PVC (Kydex) thermoplastic.
Embraer Bandeirante	Sandwich panel behind pilots with aluminum facing on cockpit side over plywood and with formica facing on the cabin side. Partitions behind pilots with fabric curtain across the center opening.
Embraer Brasilia	Partitions between cockpit and cabin and between cabin and rear baggage area. Cockpit partition has a door at the center opening. Cockpit partition is nomex honeycomb with fiberglass facing on the cockpit side and vinyl facing on the cabin side. Baggage compartment partition is composite material faced with vinyl on the passenger side and Aramid (Kevlar) cloth and polyester resin (Gilliner) on the baggage side.

No partitions.

Fairchild Metro III

Piper Navajo

Partition between cabin and rear baggage compartment. Partition of plywood and steel with vinyl facing.

Shorts 330

Partitions at the forward and rear of the cabin. forward bulkhead upper panels and the entire rear bulkhead are constructed with vacuum oven honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot nomex honeycomb core. Facings are one ply 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm). The forward bulkhead center panel is vacuum oven cure honeycomb sandwich panel with 3/8 thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Facings are two 0.1mm laminates of phenolic resin pre-impregnated glass cloth on each Decor is 0.006 inch vinyl faced with 0.001 bulkhead Forward inch PVF (Schneller Aerfilm). mouldings are vacuum oven cured multi-laminate of phenolic resin pre-impregnated glass cloth of various thickness (0.02-0.06 inches). Visible surfaces are painted with water base aircraft interior quality emulsion paint. The two flight compartment sliding doors are vacuum oven cure honeycomb sandwich panel with 3/16 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Facings are one ply 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.001 inch (Tedlar).

WALLES AND AND SOUNDED BY THE PARTY OF THE P

444

MATERIALS

Following is a tabular comparison of the various materials reported, by manufacturers or aircraft operators, as used in selected applications.

LINING MATERIALS.

estables of the second of the presence of the second of th

The description of materials represents those used at original manufacture. Refit of the interiors may result in substitution. Original Bandeirantes were fitted with leather due to its low cost, at that time, in Brazil.

TABLE 10. COMMUTER AIRCRAFT CABIN LINING MATERIALS.

Aircraft Type

Material

BAe Jetstream 3100

Lining for ceiling panels, sidewall jointstrips, passenger service unit (PSU) panel, and infill panel consists of two layers of fiberglass epoxy laminate. Ceiling panels, PSU panel and infill panel of 1/8 inch Nomex honeycomb with phenolic resin pre-preg fiberglass skins. Sidewall panels of 1/8 inch Nomex core with epoxy resin pre-preg fiberglass skins. Window reveal of 0.015 inch epoxy resin fiberglass. Decorative trim of headliners, sidewalls and PSU infill panels of PVF (Schneller Aerfilm) and Wardle Storey's Storey trim.

Beech 99

Acrylic/PVC (Kydex) with curtains of 56% rayon and 46% cotton.

Beech 1900

Acrylic/PVC (Kydex) with curtains of 56% rayon and 46% cotton.

Cessna 402

Combinations of leathers, vinyls and carpets. Sidewall upholstery backing panels of thin gauge aluminum (0.202 or less) and window escutcheons of thermoplastic sheet approximately 0.09 thick.

deHavilland Twin Otter

Lower cabin side (dado) panels of 0.025 aluminum with Naugahyde vinyl fabric and woven covered wool/nylon carpet. Sidewalls of 0.025 aluminum covered with Naugahyde vinyl fabric. Naugahyde covered ducts for cold air and 0.060 Acrylic/PVC (Kydex) covered overhead ducting.

Embraer Bandeirante

Liner of leather covered aluminum panels.

Embraer Brasilia

Kevlar*/ Nomex/ Liner of fiberglass/ moulded fiber with vinyl lining honeycomb/ carbon passenger side.

Fairchild Metro III

Nomex honeycomb.

Piper Navajo

ABS/PVC polymer (Royalite).

Shorts 330

Cabin side and door panels of vacuum oven cure honeycomb sandwich panel with core of 1/4 inch thick. 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb; facing of one 0.1mm laminate of phenolic resin preimpregnated glass cloth on each side; and decor of 0.006 inch vinyl faced with 0.001 inch PVF (Schneller

Aerfilm).

^{*} Keviar is a DuPont registered trademark.

Ceiling panels of vacuum oven cure honeycomb sandwich panels with a core of 1/4 inch thick. 1/8 inch cell. 1.5 lb./cubic foot Nomex honeycomb; facings of one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side; and decor of water base aircraft interior quality emulsion paint.

Forward exit sign boxes and forward vertical air conditioning duct covers of vacuum oven cured multi-laminate of phenolic resin pre-impregnated glass cloth (various thicknesses 0.02-0.06 inch). Visible surfaces covered with Schneller Aerfilm.

Door surrounds, framings and mouldings, and fairing pieces of vacuum oven cured multi-laminate phenolic resin pre-impregnated glass cloth (various thicknesses 0.02-0.06 inch). Visible surfaces painted with water base aircraft interior quality emulsion paint.

Window reveals and Passenger Service Unit (PSU) panels of vacuum formed polycarbonate (Lexan).

የወዘምራየው የወደር የተመደለው የተመደረገ እንደ የተመደረገ እንደ የተመደረገ እንደ የተመደረገ ለመከተለው የተመደረገ ለመከተለው የተመደረገ ለመከተለው ለመ

SOSSI "ECONOMIA" (CONTROL OF THE TOTAL OF TH

TABLE 11. COMMUTER AIRCRAFT BAGGAGE AREA LINING MATERIALS

Baggage liners are shown as original equipment. Once in service, operators report substitution of aluminum faced liners for improved durability.

Aircraft Type Material

BAe Jetstream 3100 Three layers of fiberglass with epoxy resin. Lining of Schneller Aermat (fiberglass backed vinyl). Cabin stowage compartments of honeycomb and laminate. PVF decorative trim of Schneller Aerlam and Aerfilm, Wardle Storey's Storeytrim, Oberflex's Wood Veneer (fire retardant grade) and 100% Nylon woven pile loop fabric (Langenthal Multi Point).

Beech 99 Fuselage baggage area Aluminum sheet T2024 Alclad.
0.040 thickness. Belly pod of fiberglass with no liner.

Beech 1900 Aramid (Kevlar) cloth and polyester resin (Gilliner).

Cessna 402 Standard Alclad aluminum skin substructure lined with carpeting. Some stiffening done with aluminum honeycomb and fiberglass reinforcement.

deHavilland Twin Otter Nose baggage area liner of 3/8 inch Balsawood core with fiberglass facing. Tail baggage area liner of 3/8 inch Balsawood core with aluminum liner.

Embraer Bandeirante Aramid (Kevlar) cloth 'nd polyester resin (Gilliner).

Embraer Brasilia Aramid (Kevlar) cloth and polyester resin (Gilliner).

Cabin overhead bins lined with vinyl. Floor of fiberglass with high density Nomex core, protected with corrugated aluminum sheets.

Fairchild Metro III Vinyl covered sheet aluminum.

Piper Navajo ABS/PVC polymer (Royalite).

Shorts 330

Front baggage compartment front, sides, and ceiling of vacuum oven cure honeycomb sandwich panel with a core of 3/16 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb. Rear bulkhead of front baggage compartment of light alloy honeycomb sandwich panel with a core of 1.18 inch thick, 3/16 inch cell 5056 alloy 24G L72 aluminum skin on each side.

Aft baggage compartment panels of vacuum oven cure honeycomb sandwich panel with a core of 3/16 inch thick. 1/8 inch cell. 1.5 lb./cubic foot nomex honeycomb; an inner facing of two 0.1mm laminates of phenolic resin pre-impregnated glass cloth; and a decor of 0.001 inch PVF (Tedlar).

FLOOR COVERINGS.

<u>Podostavia o presenta increso de consciona </u>

With few exceptions, wool carpeting is the material used as floor covering in the ten selected aircraft.

TABLE 12. COMMUTER AIRCRAFT FLOOR COVERINGS.

Aircraft Type	Material
BAe Jetstream 3100	Side floor panels of 0.28 inch fiberlaminate (Nomex core with epoxy skins). Center aisle panels of 0.405 inch fiberlam. Main cabin carpeting is 100% wool face yarn with 100% synthetic backing (Langenthal Melair).
Beech 99	100 % wool carpeting.
Beech 1900	100 % wool carpeting.
Cessna 402	100% wool or rubber mats.
deHavilland Twin Otter	Woven wool/nylon carpeting.
Embraer Bandeirante	Fabric carpet of operators choice.
Embraer Brasilia	Fabric carpet over carbon fiber/ nomex sandwich floor on mid-1987 and earlier aircraft. Aircraft from late 1987 changed floor to balsa wood core with fiberglass facing on each side.
Fairchild Metro III	Wool carpet.
Piper Navajo	20 inch Tiffany - tufted wool carpet with latex backing (General Motors Spec W2RB).
Shorts 330	Cabin seating area has 100 % wool, woven carpet with cut pile treated with fire retardant. Entrance/lavatory and cockpit areas have fiberglass backed vinyl floor covering (Schneller Aermat).

MAJOR TRANSPARENCIES.

Acrylic polymer, commonly called Plexiglas, is the usual material for windows in the ten aircraft. The larger aircraft feature a layer, or lam, of glass on the outer face of the cockpit windscreens or windshields. Side windows are of acrylic polymer.

TABLE 13. COMMUTER AIRCRAFT TRANSPARENCY MATERIALS

Aircraft Type	Material
BAe Jetstream 3100	Inner and outer cabin transparencies of Perspex DTD 5592 acrylic polymer sheet.
Beech 99	Single pane cabin window of 0.050 inch acrylic polymer (Plexiglas).
Beech 1900	Single laminated pane of acrylic polymer.
Cessna 402	Standard window is laminate cast acrylic polymer.
deHavilland Twin Otter	Two layer cabin windows with an inner panel of acrylic polymer and an outer panel of acrylic/PVC alloy. Outer panel thickness is 0.08 inches. Cockpit side windows of 0.25 inch Plexiglas and front windscreens acrylic polymer laminate faced with glass.
Embraer Bandeirante	Cabin windows of single pane acrylic polymer with inner scratch shield of acrylic polymer. Cockpit windshield is glass/acrylic laminate if heated.
Embraer Brasilia	Cabin and cockpit side windows of single pane. stretched acrylic polymer with inner scratch shield of acrylic polymer. Cockpit windshield is glass faced laminated polycarbonate.
Fairchild Metro III	Acrylic polymer cabin windows.
Piper Navajo	Acrylic polymer cabin windows.
Shorts 330	Flat acrylic polymer sheet (Perspex) cabin windows. Mouldel Perspex cockpit windows. Laminated acrylic faced with glass (Perplex). Earlier aircraft windshields not faced with glass.

COMMUTER AIRCRAFT SEAT MATERIALS

CABIN SEAT MATERIALS.	
Seating universally use soon to be applied. aircraft retain use of a	es urethane foam, though heat resistant wrappings These wrappings are not yet in use. Older de steel frame seating.
TABLE 1	14. COMMUTER AIRCRAFT SEAT MATERIALS
Aircraft Type	Material
BAe Jetstream 3100	Seat legs are formed sheet aluminum. Seat bottom honeycomb aluminum panel with epoxy skins. Seat is graphite epoxy resin as is the seat arm. back cushion is open cell polyurethane combined with closed cell polyurethane combined with closed cell polyurethane combined with closed cell polyurethane felt is on the cushions. Upholstery is usually 90% wool/nylon. 100% wool is used in some aircraft. Steel frame with urethane foam cushioning. 100% fabric with Zyrpro flame retardant treated co with vinyl trim.
Beech 99	Steel frame with urethane foam cushioning. 100 % fabric with Zyrpro flame retardant treated cowith vinyl trim.
Beech 1900	100% wool fabric cover with Zyrpro flame retar and vinyl trim.
Cessna 402	Pilots' seats are steel framed. Passenger frames are a composite material of Kevlar lami (Enviroform). Cushioning is polyurethane foam seat covering is 100% wool with vinyl trim.
deHavilland Twin Otter	Metal framed, urethane foam cushioned seats naugahyde vinyl trim and upholstery. K thermoplastic back panel of 0.040 inches thickness
Embraer Bandeirante	Aluminum framed, urethane cushioned, leather cov seats. On later aircraft, seat covering materia optional.
Embraer Brasilia	Aluminum/carbon fiber/Kevlar seat frame with uret cushion and fabric covering.
Fairchild Metro III	Steel and aluminum framed fiberglass bucket seats
Piper Navajo	100 % wool fabric with vinyl trim.
Shorts 330	Tubular steel frame with foam cushions on m support diaphragms. 100 % wool covers.
	31

percessi reasses harrived recogning

STALL SOSSOCIAL TREESEN

INSULATION MATERIALS.

Fiberglass cabin insulation is nearly universal in application.

TABLE 15. COMMUTER AIRCRAFT FUSELAGE INSULATION

Aircraft Type	<u>Material</u>
BAe Jetstream 3100	Cabin insulation is fiberglass Microlite PF 105W (0.6 pound per cubic foot) bagged in Orcofilm AN 18L.
Beech 99	Fiberglass.
Beech 1900	Fiberglass.
Cessna 402	Fiberglass.
deHavilland Twin Otter	Cabin not insulated.
Embraer Bandeirante	Fiberglass insulation with single coated vinyl foam tape (Scotchfoam) applied in high vibration areas such as next to the propellers. Earlier aircraft used rockwool rather than fiberglass.
Embraer Brasilia	Fiberglass insulation with single coated vinyl foam tape (Scotchfoam) applied in high vibration arcusuch as next to the propellers.
Fairchild Metro III	PVC/Nitrile foam (Ensolite) and fiberglass batting.
Piper Navajo	Fiberglass and Flexweave 1000 Cloth (fiberglass/vitreous aluminosilicate fibers with organic binders).

WIRE INSULATION MATERIALS.

Shorts 330

Wiring conforms to various military specifications. Only in the Shorts 330 is use of Kapton insulated wiring reported.

Sound and thermal insulation of water repellant fiberglass with phenolic resin binder 0.61 lb./cubic

nylon reinforced PVF film (on later aircraft).

Covering of neoprene coated nylon cloth or

TABLE 16. COMMUTER AIRCRAFT WIRING INSULATION

Arcraft Type

Material

BAe Jetstream 3100

Cabin and flight deck wiring as follows: (Raychem Specification 44) - Specification Standard -MIL-W-81044; cables MIL-C-27500 and MIL-C-Type 2 (PTFE) Equipment wire - Specification 7078. Standard BSG 210. ISO 2032 and DEF STAN 61-12 Part 8 MIL-W-16878. 5 (Aluminum cable) Type Specification Standard - BNAE: L52-120, L52-125. Type 1 is the majority of the wiring. Type 2 used in Type 5 is used for some internal panel wiring. starter/generator feeders in wing and cabin areas.

Beech 99

Proposed Property property seconds 15000000

Cabin and flight deck wiring routing, type and clamping in accordance with MIL-W-5088A. Non-shielded stranded wire of MIL-W-5086B or MIL-W-81044/9. Shielded stranded wire of MIL-C-7078B Class 4 or MIL-C-27500. Teflon insulated or high temperature stranded wire of MIL-W-22759/7. MIL-W-22759/8. MIL-W-25038, MILSPEC 17411, or MIL-W-16878D Type E. MIL-W-16878D Type E wire is not to be used in any harness which is supported by the structure or any application where it is exposed to abrasion.

KKKKKI KKNISI VIVIUI BERISK VIIKKI KERKKI BRISKI BERISKI KEKSKI VILAKI KUESKI KUESKI KESISKI KESISKI KERK

Beech 1900

Cabin and flight deck wiring routing, type and clamping in accordance with MIL-W-5088A. Nonshielded stranded wire of MIL-W-5086B or MIL-W-81044/9. Shielded stranded wire of MIL-C-7078B Class or MIL-C-27500. Teflon insulated or temperature stranded wire of MIL-W-22759/7, MIL-W-227 59/8, MIL-W-25038, MILSPEC 17411, or MIL-W-16878D MIL-W-16878D Type E wire is not to be used in any harness which is supported by the structure or any application where it is exposed to abrasion. All wiring of MIL-W-22759 and shielded wiring of MIL-C-27500.

Cessna 402

Cabin and flight deck wiring of MIL-W-81044/9 (Polyalkene-inner and polyvinylidene fluoride-outer). MIL-W-5086B/2 (Polyvinyl chloride-inner and glass-nylon jacket). MIL-W-81044/12 (Polyalkeneinner and polyvinylidene fluoride-outer. MIL-W-22759/8 MIL-W-5086A/1 (Polytetrafluoroethylene). (Polyvinylchloride-inner and extruded clear nylon (Polytetrafluoroethylene). MIL-W-22759/2 MIL-W-16878E/4 (Per Specification depending on "/X" number). Polytetrafluoroethylene (TFE) when specified conforms to L-P-403. Type III (ASTM-D-1457-83).

deHavilland Twin Otter Cabin and flight deck wiring of MIL-W-5086 and MIL-W-

22759/13.

Embraer Bandeirante Cockpit avionics wiring is Tefzel extruded insulation

of MIL-W-22759/35 24 gauge wire. Airframe wiring is MIL-W-5086/1 and /2 wiring with polyvinylchloride (PVC) insulation. High temperature wiring used in engine nacelles is MIL-W-22759/6 Polytetrafluoro-ethylene (TFE) insulated. Fire resistant nacelle

wiring is MIL-W-25038 TFE insulated.

Embraer Brasilia All wiring MIL-W-22759(TFE).

Fairchild Metro III Ethylenetetrafluoroethylene (ETFE).

Piper Navajo Cabin wiring since, 1980 MIL-W-81044/9; prior to 1980

MIL-W-5086/7. Flight deck wiring MIL-W-25038B.

Shorts 330 Cabin and flight deck wiring of three layers: PVC

inner, glass braid center and nylon outer. On later aircraft, size 22 wire has polyimide (Kapton)

insulation.

FUSELAGE SKIN THICKNESS.

Fuselage skin thickness of the cabin areas of the ten commuter aircraft is illustrated in figures 12 through 21. Thicknesses shown in the illustrations are measured in inches, e.g., .040 or .025 equal 0.04 inches and 0.025 inches.

possi Percessa Printing Personal Pasteest Ferencia Conscient Desposit Losiosia Desposit Personal Personal Dise

FIGURE 12. BAE JETSTREAM 3100 FUSELAGE SKIN THICKNESS

ONTO SIGNAL SILLIS LIGARE LOUGE POSTER LOUGE PROPER POSTER POSTER POSTER POSTER POSTER POSTER POSTER POSTER




FIGURE 13. BEECH 99 AIRLINER FUSELAGE SKIN THICKNESS

SCORPORA DESCRIPTION OF THE PROPERTY OF THE PR

FIGURE 14. BEECH 1900 AIRLINER FUSELAGE SKIN THICKNESS

THE COME STATE OF STA

Keesser Keesser




FIGURE 15. CESSNA 402 FUSELAGE SKIN THICKNESS




FIGURE 16. TWIN OTTER SERIES 300 FUSELAGE SKIN THICKNESS

CONCRETE PRESENCE PRESENCE PRINCIPAL PRESENCE PRESENCE PRINCIPAL PRINCIPAL





FIGURE 18. EMBRAER BRASILIA FUSELAGE SKIN THICKNESS

FIGURE 19. FAIRCHILD METRO III SKIN THICKNESS

THE SOOR STANDED THE SECOND DESCRIPTION NAMED AND SECOND DESCRIPTION OF THE PERSON DESCRIPTION O



*NOTE: MATERIAL IS ALL 2024-T3 ALUMINUM EXCEPT WHERE NOTED BY *, WHICH IS 2024-T4 ALUMINUM (HEAT TREATED AFTER FORMING)

FIGURE 20. PIPER NAVAJO FUSELAGE SKIN THICKNESS

X 200

000000

MANAGER PASSAGES PASSAGES

Address percent




FIGURE 21. SHORTS 3-30 FUSELAGE SKIN THICKNESS

SYSTEMS

FIRE DETECTION.

Types of fire detection systems vary, but new and larger aircraft feature continuous loop sensors featuring heat sensing through a pressurized gas. Embraer and Shorts aircraft feature baggage compartment smoke detectors; Beech offers these as an option on the Beech 1900.

TABLE 17. COMMUTER AIRCRAFT FIRE DETECTION SYSTEMS

Aircraft Type	Descriptions
BAe Jetstream 3100	Fault Free Fire Detection (FFF) type system of Graviner HTL-heat sensing fire wire detecting changes in wire capacitance. System located in each engine nacelle.
Beech 99	Three photo-conductive cells sensitive to infrared rays are located in each nacelle and in the cabin center aisle floor aft of the main wing spar. Optional smoke detectors were available for the nose avionics compartment and adjacent to fuselage fire detectors.
Beech 1900	Temperature sensitive fire-loop located in each nacelle.
Cessna 402	Three heat sensitive detectors located in each engine nacelle.
deHavilland Twin Otter	Four thermal switches located in each engine nacelle.
Embraer Bandeirante	Two photocell smoke detectors in the cabin area and one in the baggage area. Older aircraft with three bimetallic heat sensors in the engine nacelles; newer aircraft have closed loop, pressurized gas heat sensing loops in the nacelle.
Embraer Brasilia	Cabin/baggage compartment smoke detectors in a labyrinth assembly containing a constant light source, a photocell, a test light and associated circuitry; two located in the cabin ceiling, one in the baggage compartment ceiling and one under the baggage compartment flooring. Engine nacelles have three heat sensors - one in the accessory section, one in the exhaust area and one in the landing gear wheelwell. Another heat sensor is located on the auxiliary power unit in the tail.

Fairchild Metro III Bi-metal heat sensors in the engine compartments.

Piper Navajo Chieftain (piston powered) has no installed detection system. Turbine powered Navajo

PA-31-1040 has three 450 degree fahrenheit thermal

sensors in each engine compartment.

Shorts 330 Cabin smoke detectors: 2 in the forward cabin area,

two in the aft cabin area and one in the baggage compartment. Both engine nacelles equipped with heat

sensitive continuous-loop wire detectors.

FIRE SUPPRESSION.

Fire suppression for engines and auxiliary power units (APU) uses Halon 1301, except in the Shorts 330.

TABLE 18. COMMUTER AIRCRAFT FIRE SUPPRESSION SYSTEMS

Aircraft Type	Descriptions
BAe Jetstream 3100	Two fire bottles in each main wheelwell. Each bottle contains 4.5 pounds CBrF3 (Bromotrifluoromethane) / Halon 1301 charged by dry nitrogen. No discharge duration specified.
Beech 99	One cylinder containing 2 pounds of Halon located in each engine nacelle. Nozzled into the engine compartment with approximate discharge duration of 5 seconds.
Beech 1900	Two cylinders in each engine nacelle each containing 2 pounds of Halon and each with a discharge duration of approximately five seconds. Cylinders are discharged one at a time allowing up to four "shots" for one engine.
Cessna 402	One bottle in each nacelle containing 2.1 pounds Halon 1301 (Bromotrifluoromethane) with a discharge duration of no more than 2 seconds.
deHavilland Twin Otter	American Standard system of one bottle in each nacelle of 1.37 pounds Halon 1301 (CBrF3 - Bromotrifluoromethane) charged to 450 psi at 70 degrees Fahrenheit. Discharge duration not specified.

Embraer Bandeirante Aircraft complying with SFAR 41 have one 2.5 1b. bottle of Halon 1301 in each wheelwell useable in each engine. Bottle provides a single charge of Halon to the engine accessory section. Embraer Brasilia 6.5 pounds of Halon 1301 agent (CBrF3 Bromotrifluoromethane) per engine nacelle for the engine and wheelwell, and one one pound bottle of Halon 1301 at tail mounted APU. No discharge specified. Fairchild Metro III One Halon 1301 (Bromotrifluoromethane) bottle with an agent amount of 3.5 pounds and a discharge duration of five seconds. Piper Navajo Navajo Chieftain has no engine fire suppressions The Navajo PA-31-1040 has a Halon 1301 system in each nacelle. Approximate discharge duration of four seconds. Shorts 330 Four bottles of Halon 1211, two in each wing aft of the engine nacelle. 2.0 pound charge of agent per bottle. No discharge duration specified.

ANDREA FERENT MANAGE PARAMET KESKAM BRAKKA PINAMET

1333333 1333333 13333333

HAND EXTINGUISHERS.

Halon 1211 fire extinguishers have been installed in each aircraft except the EMB-110 Bandeirante. New Bandeirantes are not currently sold in the U.S. Operators may upgrade, voluntarily, to Halon 1211 extinguishers. In the Shorts 330 the Halon 1211 extinguishers can be directed into baggage areas through special couplings and tubing manifolds.

TABLE 19. COMMUTER AIRCRAFT HAND FIRE EXTINGUISHERS

Aircraft Type	Descriptions
BAe Jetstream 3100	Two extinguishers, one in the cockpit to the left of the left seat and one in the cabin behind the aft right passenger seat. Nitrogen charged Halon 1211 (BCF) with the cockpit bottle holding 5.4 pounds of agent and the cabin bottle holding 6.3 pounds of agent.
Beech 99	Two extinguishers, one under the right cockpit seat and one behind the aft left or right passenger seat in the cabin. Each bottle is a two pound Halon 1211 bottle.

Beech 1900	Two 2 pound Halon 1211 bottles, one under the right cockpit seat and the other next to the front entry door.
Cessna 402	One 2.5 pound Halon 1211 bottle beneath the right cockpit seat.
deHavilland Twin Otter	Two 2 pound Halon 1211 bottles, one on the cockpit floor between the seats and one on the right half of the passenger cabin door.
Embraer Bandeirante	A 2.2 pound carbon dioxide extinguisher bottle mounted on the pilot's seat back and one dry chemical extinguisher bottle behind the rear passenger seat and mounted on the bulkhead (SFAR 41 aircraft).
Embraer Brasilia	Two 2.5 pound Halon 1211 bottles, one behind the left cockpit seat and the other below the flight attendant seat at the forward entry door.
Fairchild Metro III	Two 2.5 pound Halon 1211 bottles, one behind the left cockpit seat and the other next to the front entry door.
Piper Navajo	One 2.5 pound Halon 1211 bottle under the right cockpit seat.
Shorts 330	Two 2 pound Halon 1211 bottles. one behind the right cockpit seat and one on the emergency hatch above the right rear exit door (by the galley).

ENTERN ENTERN ENTERN PROPER PRODUCT SERVICE VONDORS PERSONS PROPERTY DAYS BOTTON

OXYGEN SYSTEMS.

ঽ¥₵₢₢₲₠₯₢₭₢₭₵₭₯₢₭₲₲₲₢₽₽₽₲₲₢₺₯₯₺₢₢₼₲₢₺₲₺

<u> KSSSACON KAYAYAYA A XOOCAANAA KAAAAA A XAXXAAAA A</u>

For nine of the ten commuter aircraft, use of cylinders of compressed (1850 psi) oxygen is standard. The Embraer Brasilia may be fitted with an optional oxygen system featuring oxygen generators; this installation is not common. Each, except the Shorts 330, either has or can have a fixed oxygen system installed. The Shorts 330 uses only two supplementary oxygen bottles for the pilots and passengers. The Bandeirante and the Twin Otter normally are equipped only with a portable oxygen bottle for each pilot.

TABLE 20. COMMUTER AIRCRAFT OXYGEN SYSTEMS

Aircraft Type

Descriptions

BAe Jetstream 3100

EROS 1409 liter (49.8 cubic foot) system. Cylinder storage behind the aft pressure bulkhead with line routing next to the cabin wall behind paneling and insulation. No special protective measures. Monel or stainless steel oxygen lines.

Beech 99

Cylinder storage in the nose. Lines routed overhead in the cabin with the cited protective measure being routing of oxygen lines away from other types of system lines. Lines of stainless steel with some aluminum.

Beech 1900

Twin cylinder storage, in the nose, of 76.5 cubic feet of compressed oxygen. Overhead line routing in the cabin wall away from other lines and behind paneling and insulation. Lines of stainless steel and some aluminum.

Cessna 402

Cylinder storage, in the nose, of 44 cubic feet of compressed oxygen (114.9 cubic foot optional system). Lines routed on the left side and top of cabin. Lines of 5052-0 and 6061-0 aluminum. Cessna design specification requires oxygen system installation not be in close proximity to fuel, oil and hydraulic systems. It is further directed that oxygen systems will not be contaminated by leaking fuel, oil and hydraulic fluids. The oxygen lines, fittings and equipment are required to be at least six inches away from fuel, oil and hydraulic systems. Deflector plates are stipulated where necessary to keep fuel. hydraulic fluids from oxygen Heating system ducts must be routed components. apart from oxygen system components or insulated to prevent heating of the oxygen system.

deHavilland Twin Otter

Commuter Twin Otters normally were not equipped with oxygen systems.

Embraer Bandeirante

Two portable cylinders (1850 psi and 115 cubic feet) for the pilots.

Embraer Brasilia

Cylinder storage of compressed oxygen (39 cubic feet at 1850 psi) in the flight attendant cabinet at the front of the cabin, supplemented by portable oxygen cylinders behind the right cockpit seat and next to the flight attendant seat. Line routed along the top of the cabin. Standard passenger oxygen system is portable cylinders with two outlets each (adequate for 10 percent of cabin occupants). oxygen chemical system consists of optional generators supplying oxygen for all occupants. There is one additional portable cylinder at the flight attendant station for therapeutic use.

Fairchild Metro III

High pressure (2000 psi) oxygen cylinder storage aft of the cargo compartment. From the cylinder to the selector valve the lines are routed along the side of the cabin between the inner liner and the skin. From the selector valve to the users the lines are run overhead in the cabin between the inner liner and the skin. Lines have local chafe guarding and threading compound is in accordance with Mil-T-5542B. Lines are of aluminum, steel, and copper. Passenger distribution lines are of nylon.


Piper Navajo

Cylinder storage of either 22 or 115 cubic feet of compressed oxygen in either the tail or nose. Lines are routed down the top center of the fuselage and are mounted in chafe grommets at passages through bulkheads. Lines are of 5050-0 aluminum.

Shorts 330


No fixed system is installed. Portable oxygen is available and stored in one bottle in the aft cabin storage area on the left side and at the right hand cockpit entrance from the cabin.

Fire suppression, fire detection, and oxygen systems are illustrated in figures 22 through 30. Figure 31 illustrates fire detection and suppression systems. Figure 32 illustrates oxygen system, and figure 33 illustrates fire suppression, fire detection, and oxygen systems.



FIRE SUPPRESSION, AND OXYGEN SYSTEMS BAE JETSTREAM 3100 FIRE DETECTION, 22. FIGURE

KSSI **SHESS** JULUSH SAMAS SESSOO TAMAS MULLINGSE JULUSH SESSOO TAMAS KAS



BEECH 99 AIRLINER FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS 23. FIGURE

and same same mane man man same week same same same same same same

24. BEECH 1900 AIRLINER FIRE DETECTION & SUPPRESSION SYSTEMS FIGURE







FIGURE 25. BEECH 1900 AIRLINER OXYGEN SYSTEMS





FIRE DETECTION, FIRE SUPPRESSION, 27. TWIN OTTER SERIES 300 AND OXYGEN SYSTEMS FIGURE

produced possessed prosessed bestscoop prosessed prosessed possessed possessed



EMBRAER BANDEIRANTE FIRE DETECTION & SUPPRESSION SYSTEM **5**8. FIGURE

POST XXXXXX INDICOS EDSDOTA PARAMON INDITIONS MINISTER PROVINCE PR





FIGURE 29. EMBRAER BRASILIA FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS



FIRE SUPPRESSION, AND OXYGEN SYSTEMS 30. FAIRCHILD METRO III FIRE DETECTION, FIGURE

STORTED SOLVEN SOLVEN STREET, LUCIUM SESSION ROOMER BROSSON KEESSES FINANCE BUCK

Sec. 1.




FIGURE 31. PIPER NAVAJO 1040 (TURBINE) FIRE DETECTION AND SUPPRESSION SYSTEMS

ESSOSSES ESSOSSES DESCRIPTION

SAME TO SAME TO COLORER TO LOCAL SPECIAL PROPERTY

12.000 SSSSSSS





FIGURE 32. PIPER NAVAJO OXYGEN SYSTEM

Kang Panang manng antong meneng banang mannan pantong banang pantong banang banang manng man



33. SHORTS 3-30 FIRE DETECTION, FIRE SUPPRESSION AND OXYGEN SYSTEMS FIGURE

STATES ASSESSED SECTIONS

2000

20222

VENTILATION SYSTEMS.

Older and smaller aircraft are unpressurized. Where the aircraft is turbine powered, engine bleed air is used for air conditioning and heating. Reciprocating engined aircraft, (CE-402 and Piper Navajo) use gasoline combustion heaters to warm the cabin air. These heaters are not equipped with fire detection or suppression systems.

TABLE 21. COMMUTER AIRCRAFT VENTILATION SYSTEMS

Aircraft Type

Descriptions

BAe Jetstream 3100

Pressurized aircraft with engine bleed air used for heated and cooled air, or with plain ram airflow of outside air. The air outflow is through a valve at Air charge occurs in the rear pressure bulkhead. 2.17 minutes at 25,000 feet and 1.51 minutes at sea Air outflow rate is a Mass Flow Rate of 20 pounds per minute and Volume Flow Rate of 333 cubic per minute at 25.000 feet. At sea level the Mass Flow Rate is 36 pounds per minute and Volume Flow Rate is 480 cubic feet per minute. material is of aluminum alloy, G.R.P. and proprietary lightweight ducting. G.R.P. is glass reinforced plastic -- in this case two layers of fiberglass Flexible ducting of cloth with phenolic resin. polyurethane coated nylon fabric supported by PVDF (polyvinyl difluoride) filament. Floor ducting of 0.28 inch fiberlaminate (Nomex core with fiberglass skins).

Beech 99

STATE OF THE PROPERTY OF THE P

Unpressurized aircraft using ram air flow. Time for air change is 30 to 60 seconds depending on ram pressure. The air outflow location is an exhaust at the rear of the fuselage and the outflow rate is not specified. Duct material is fiberglass.

Beech 1900

Pressurized aircraft using either ram airflow or engine bleed air for heated or cooled air. Time for air change is 30 to 60 seconds, depending upon pressure differential with the air outside the cabin. The outflow valves are located in the aft cabin with outflow rate not specified. Duct material is fiberglass.

Cessna 402

Unpressurized aircraft using ram airflow from nose and dorsal fin intakes. Time for air change is variable depending upon adjustment of ventilation controls. Air outflow is through an exhaust at the rear of the cabin. Duct materials are fiberglass, aluminum sheet metal, flexible rubber ducting and some thermoform plastics.

deHavilland Twin Otter

Unpressurized aircraft using ram airflow collected from a scoop beneath the cockpit and distributed through a ducting system. Heat for the ram air is obtained from engine bleed air. Airflow rates are not known. Air exits from an exhaust at the top of the cabin center. Duct materials are 0.060 and 0.080 polycarbonate (Lexan).

Embraer Bandeirante

Unpressurized aircraft using engine bleed air for circulation after heating or cooling. Ram air circulation is obtainable with two NACA air inlets in the dorsal fin providing the air source.

Embraer Brasilia

Cabin and cockpit are supplied by separate air ducting with cross connecting capabilities. Pressurized (7.2 psi) aircraft using ram airflow and engine or APU bleed air for heating and cooling of recirculated air. Composite material ducting reinforced with fiberglass.

Fairchild Metro III

Pressurized aircraft (7.0 psi) using ram air and engine bleed air for heating and cooling of airflow. Bleed air from a single engine yields a time for air change of less than 6 minutes, while using dual engine bleeds yields a change in less than 3 minutes. The outflow valve is located in the aft pressure bulkhead behind the cargo compartment. Air outflow rate is 22 lbs. minimum with the rate dependent outside air temperature, cabin temperature, cabin altitude, pressure altitude, throttle settings and the number of environmental control unit (ECU) packs operating. Duct material is aluminum and silicone impregnated fiberglass.

Piper Navajo

Unpressurized aircraft using ram airflow. Outflow location is venting at the tail with no rate specified. Ducting is of fiberglass.

Shorts 330

Unpressurized aircraft using ventilation blowers and no ram air. Time for air change is unspecified and outflow is from the rear of the cabin at a rate of 15 to 25 lb. per minute. Duct material is reinforced, insulated plastic.

Figures 34 through 43 illustrate ventilation systems.





FIGURE 34. BAE JETSTREAM 3100 VENTILATION SYSTEM


KESI MININI ANNON SOSSII SEEKESI MEETET MAKKEI MAKKEI MAKKEI EKKEMI EKKEMI MAKKEI MAKKEI KEE



PARTICION DESCRIPTION PROCESSOR SECRETARY DESCRIPTION

Secret Commercial Comm

FIGURE 35. BEECH 99 AIRLINER VENTILATION SYSTEM



MANASA BOOMER NO MANASA

SOCIOLO SECENCIA DOS SECONO

5355577

555555665 25555555






FIGURE 37. CESSNA 402 VENTILATION



postal Described and Control of the Control of the


TWIN OTTER SERIES 300 VENTILATION SYSTEM 38. FIGURE



39. EMBRAER BANDEIRANTE VENTILATION FIGURE

STATION STATISTICAL MONTHS PROPERTY STATISTICS PROPERTY PARTY IN THE PROPERTY PROPER

ATTER SECURIS STATES






FIGURE 41. FAIRCHILD METRO III VENTILATION SYSTEM




FIGURE 42. PIPER NAVAJO VENTILATION SYSTEM




FIGURE 43. SHORTS 3-30 VENTILATION SYSTEM

KELLIKET ESIONNET KINNKIN, DEBERRET KRESSENT HENSENET KOKKKET HINE

STAIN PROPER NOVEMENT SERVICE

SUMMARY

The ten commuter aircraft selected for this study represent not only those aircraft most common in the commuter fleet, but also are representative of those most commonly being delivered to operators. The ten commuter aircraft in this study represent the majority of the current regional airline fleet of aircraft carrying thirty or fewer passengers, and, due to their numbers in service (880 out of 1100 commuter class aircraft), will be representative of the population for several more years.

The aircraft in this study illustrate trends in the commuter aircraft industry. The Cessna 402 and Piper Navajo originated as general aviation aircraft designed some years ago. They are relatively small, piston powered and simple in both design and materials applications. In the case of the Navajo, a turbine engine version has recently been placed on the market as a means of keeping the airframe saleable. The piston powered Navajo is not required to be equipped with engine fire detection and suppression capability while the turbine powered version is.

Of the other and larger eight aircraft, the deHavilland Twin Otter came into service in the late 1960s. It is also a very simple aircraft with, as an example, no cabin insulation. It is larger than newer aircraft of similar capacity, a characteristic derived from its development as an aircraft able to serve as the means of transportation and supply for remote, undeveloped areas. Both the Twin Otter and its contemporary, the Beech 99, are at the end of their delivery periods. Each is a derivative of older aircraft which were adapted to commuter service. Relatively new thermoplastics have been applied in each of these two aircraft, on a limited basis. The Embraer Bandeirante, though of new design, is not being delivered currently due to cost and market desire for larger aircraft.

In the other six aircraft, application of more modern materials is a major characteristic of the designs of the aircraft. The Fairchild Metro III makes some use of plywood as a core material to certain dividers, however, the predominant trend is to newer materials. The Shorts 330 is a large aircraft that features an interior purposefully appearing like that of airline aircraft operated by Part 121 commercial carriers. The Shorts 330, the Embraer Brasilia, the Metro III and the Beech 1900 each feature large, rear located, separate baggage compartments, leaving the cabin for seating. Only in the Shorts 330 and the Brasilia are there overhead storage bins installed.

Of the ten aircraft, only the Shorts 330 has a large interior that allows standing headroom in its large interior volume. The other aircraft, are much more compact, with interior storage limited to bins at the entry end of the aircraft.

Weight saving and durability seem to be keys to design success. possibly affecting the selection of various new thermoplastics and composite materials for the interiors. Each was originally delivered with polyurethane cushions; currently operators and manufacturers are involved in covering these cushions with fire blocking materials to upgrade fire safety.

The two piston powered aircraft use gasoline fired heaters without fire detection or fire suppression capability to provide cabin heat and ram air flow to provide outside air for cabin and cockpit cooling. The remainder of the aircraft are turbine powered, turboprop aircraft that use engine bleed air for heating and cooling of the interior air. The Beech 99, Cessna 402, deHavilland Twin Otter, Embraer Bandeirante, Piper Navajo and Shorts 330 are unpressurized aircraft while the BAe Jetstream 3100, Beech 1900, Embraer Brasilia and Fairchild Metro III are of pressurized design. The four pressurized aircraft are of newer design. The unpressurized aircraft have oxygen available for the pilots and passengers, often in portable storage form. The pressurized aircraft feature cabin oxygen for the passengers. Each of these aircraft reflects their operating environment of short, low altitude flight legs, not requiring design of oxygen systems characteristic of large commercial aircraft. In some of the aircraft, the fixed oxygen system is an option picked only by operators faced with the need for sustained high altitude operations, such as in mountainous areas. In these aircraft, oxygen is meant for emergency use of the crew and individual passengers with a temporary need.

The overall trend in the design of commuter airliners, as seen in this sample, is that of increasing sophistication in application of materials, in the newer aircraft, similar to that found in large commercial aircraft. With the exception of the deHavilland Twin Otter and the Shorts 330, these aircraft are small and offer relatively high performance.

APPENDIX

STANDARD DISTRIBUTION

Civil Aviation Authority (5) Aviation House 129 Kingsway London WC2B 6NN England			DOT-FAA AEU-500 (4) American Embassy APO New York, NY 09667		
Embassy of Australia (1) Civil Air Attache 1601 Mass. Ave. NW Washington, DC 20036			University of California (1) Service Dept Institute of Transportation Standard Lib 412 McLaughlin Hall Berkely, CA 94720		
Scientific & Tech. Info FAC (1) ATTN: NASA Rep. P.O. Box 8757 BWI Airport Baltimore, MD 21240			British Embassy (1) Civil Air Atache ATS 3100 Mass. Ave. NW Washington, DC 20008		
Northwestern University (1) Trisnet Repository Transportation Center Library Evanston, ILL 60201			Director DuCentre Exp DE LA (1) Navigation Aerineene 941 Orly, France		
ANE-40	(2)	ACT-61A	(2)	ASW-53B	(2)
ASO-52C4	(2)	AAL-400	(2)	AAC-64D	(2)
APM-13 Nigro	(2)	M-493.2 B1dg.10A	(5)	ACE-66	(2)
AEA-61	(3)			ADL-1	(1)
ADL-32 North	(1)	APM-1	(1)	ALG-300	(1)
AES-3	(1)	APA-300	(1)	ACT-5	(1)
ANM-60	(2)	AGL-60	(2)	AWS-100	(1)

ACT-300 Distribution

DOT/FAA National Headquarters APA-300 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA Great Lakes Region (2) AGL-60 O'Hare Office Center 2300 East Devon Avenue Des Plaines, IL 60018

DOT/FAA Southwest Region (2) ASW-53B P.O. Box 1689 Fort Worth, TX 76101

DOT/FAA Mike Monroney Aeronautical Center (2) AAC-64D P.O. Box 25082 Oaklahoma City, OK 73125

DOT/FAA Central Region (2) ACE-66 601 East 12th Street Federal Building Kansas City, MO 64106

DOT/FAA National Headquarters ADL-1 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters ALG-300 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA Technical Center Public Affairs Staff, ACT-5 Atlantic City Int'1 Airport, NJ 08405

DOT/FAA National Headquarters ASF-1 800 Independence Avenue, SW. Washington, DC 20591 DOT/FAA National Headquarters ASF-100 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA Nationa Headquarters ASF-200 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters ASF-300 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters AST-1 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters ADL-2A 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters AVS-1 800 Independence Aveneu, SW. Washington, DC 20591

DOT/FAA National Headquarters AFS-1 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters ASF-200 800 Independence Avenue, SW. Washington, DC 20591

DOT/FAA National Headquarters AWS-1 800 Independence Avenue, SW. Washington, DC 20591

ACT-300 Distribution

FAA, Chief, Civil Aviation (1)
Assistance Group, Madrid Spain
c/o American Embassy
APO-New York 09285-0001

Dick Tobiason (1) ATA of America 1709 New York Avenue, NW. Washington, DC 20006

FAA Anchorage ACO 701 C Street, Box 14 Anchorage, Alaska 99513

FAA Atlanta ACO 1075 Inner Loop Road College park, Georgia 30337

FAA Boston ACO 12 New England Executive Park Burlington, Mass. 01803

FAA Brussels ACO % American Embassy, APO, New York, NY 09667

FAA Chicago ACO 2300 E. Devon, Room 232 Des Plains, Illinois 6008

FAA Denver 10455 East 25th Ave., Suite 307 Aurora, Colorado 98168

Frank Taylor 3542 Church Road Ellicott City, MD 21403

Mr. Gale Braden (FAA) 5928 Queenston St. Springfield, VA 22152

Richard E. Livingston, Jr.
Director, Aerotech Operations for
the IAPA Group
1805 Crystal Drive, Suite 1112 South
Arlington, VA 22202

Al Astorga (1)
Federal Aviation Administration
(CAAG)
American Embassy, Box 38
APO-New York 09285-0001

Burton Chesterfield, DMA-603 (1) DOT Transportation Safety Inst. 6500 South McArthur Blvd. Oklahoma City, OK 73125

FAA Forth Worth ACO P.O. Box 1689 Fort Worth, TX 76101

FAA Long Beach ACO 4344 Donald Douglas Drive Long Beach, CA 90808

FAA Los Angeles ACO P.O. Box 92007, Worldway Postal Center Hawthorne, CA 90009

FAA New York ACO 181 So. Frankline Ave., Room 202 Valley Stream, NY 11581

FAA Seattle ACO 17900 Pacific Highway South, C-68966 Seattle, Washington, 98168

FAA Wichita ACO Mid Continent Airport, Room 100 FAA Bldg. 1891 Airport Road Wichita, KA 67209

Dr. Hans A. Krakauer Deputy Chairman, International Airline Pilots Association Group Apartado 97 8200 Albufeira, Portugal

Geoffrey Lipman
Executive Director, President du Conseil
International Foundation of Airline
Passenger Associations
Case Postale 462, 1215 Geneve
15 Aeroport, Suisse, Geneva

Mr. Fred Jenkins, ANM-130L Federal Aviation Administration 4344 Donald Douglas Drive Long Beach, California 90808

Mr. Dan Gross B-66 Technology Building National Bureau of Standards Washington, DC 20234

Dr. James M. Peterson
The Boeing Company
MS/73-43
Seattle, Washington 98124

Dr. John O. Punderson E.I. Dupont De Nemours P.O. Box 1217 Parkersburg, West VA 26102

property of the property of th

Commander
U.S. Army AVSCOM
Attn: DRSAV-EI (Mr. John P. Dow)
4300 Goodfellow Blvd.
St. Louis, MO 63120

Mr. L. C. Virr Civil Aviation Authority Barbazon House Redhill Surrey RHI ISQ England

Mr. Ray Young Engineering and Air Safety Dep't Airline Pilots Association 1625 Massachusetts Ave., NW Washington, DC 20036

Dr. Calyton E. Hathaway Monsanto Company 800 N. Lindberg BLvd. Mail Zone R3B St. Louis, MO 63166

Dr. Leo P. Parts Monsanto Research Corp. 1515 Nicholas Road Datyton, Ohio 45407 Mr. Matthew M. McCormick National Transportation Safety Board Bureau of Technoloty Washington, DC 20594

Mr. A. Delman
The Wool Bureau, Inc.
Technical Services Center
225 Crossways Park Drive
Woodbury, L.I., New York 11797

Dr. L. Benisek
International Wool Secretariat
Technical Center, Valley Drive
Ilkley, West Yorkshire, LS29 8PB
England

Mr. John A. Leland Username: Dept E-29 Douglas Aircraft Co. 35-14 3855 Lakewood Blvd. Long Beach CA 90846

Mr. Stan Ames Fire Research Station Borehamwood Hertfordshire WDG 2BL England

Mr. Arthur G. Thorning Civil Aviation Authority CAA House 45-59 Kingsway London WC2B GTE England

Mr. Lee Hoyt Weber Aircraft Co. 2820 Ontario Street Burbank, CA 91505

Julia M. Baer Celanese Fibers Marketing Comp. P.O. Box 32414 Charlotte, NC 28232

Mr. James O. Price Heath Tecna Corp. 19819 84th Avenue South Kent, Washington 98031 Mr. Richard M. Harrison Custom Products Company P.O. Box 699 Sun Valley, California 91352

Mt. T. E. Waterman IIT Research Institute 10 West 35th Street Chicago, Illionis 60616

Mr. Henri Branting FAA Headquarters AWS-120 800 Indepednce Avenue SW Washington, DC 20591

Dr. James E. Mielke Science Policy Research Div. Congressional Research Services Library of Congress Washington, DC 20540

Mr. Thomas Madgwick
British Areospace p.l.c.
Aircraft Group
Weybridge-Bristol Division
Filton House
Bristol BS99 7AR Englang

Mr. Joseph L. Buckley Factory Mutual System 1151 Boston-Providence Turnpike Norwood, Mass. 02062

Mr. John Hoffmann
Port of New York & New Jersey
Authority
One Path Plaza (4th Floor)
Jersey City, NJ 07306

Mr. Robert E. Kraus
Raychem Corp.
300 Constitution Drive
Menlo Park, California 94025

Mr. John A. Blair Manager, Standards E.I. Dupont deNemours & Co.; PP+R Chestnut Run Wilmington, Delaware 19898

<u>የጀትዮጵያ የአስተዋ</u>ቸው የተመሰው የተመሰው

Mr. Bill Martinez, Mgr. Data Service AMI Industries, Inc. P.O. Box 370 Colorado Springs, California 80901

Mr. J. J. Brenneman Fire Protection Engineer United Airlines, Inc. P.O. Box 66100 Chicato, Illionis 60666

Mr. Edward L. Lopez Lockheed Aircraft Corp. Dept. 74-75, Bldg. 229-A Box 551 Burbank, CA 91503

Dr. D. Kourtides Chemical Research Center NASA/AMES Research Center Moffett Field, CA 94035

Mr. C. Hayden Leroy TE-10 Bldg. 10-A National Transportation Safety Board Washington, DC 20594

Mr. Richard Nelson ANM-110 17900 Pacific Highway South C-G8966 Seattle, WA 98168

Dr. Charles R. Crane FAA, CAMI, AAC-114 P.O. Box 25082 Oklahoma, OK 73125

Mr. Reginald Utting
The Boeing Company
Commercial Airplane Group, 747 Div.
P.O. Box 3707
Seattle, Washington 98124

Dr. Joseph C. Reed E.I. Dupont de Nemours & Co. Plastics Department Fluorocarbons Division Wilmington, Delaware 19898 Dr. Fumiharu Saito
Building Research Institute
Ministry of Construction
Tatehara-l Oho-Machi
Tsukuba-Gun
Ibaraki Prefecture, Japan

Dr. Robert Keith
Laboratory Industrial Medicine
Eastman Chemical Company
Kingsport, Tenn. 37662

Mr. Kenton D. Warner Puritan-Bennet Aero Systems Co. 10800 Pflumm Road Lenexa, Kansas 66215

Mr. Geroge Veryioglou Systems Technology Staff Boeing Commercial Airplane Co. P.O. Box 3707, MS 77-70 Seattle, WA 98124

Mr. Donald Schroeder Federal Aviation Administration APM-710 800 Independence Ave. SW Washington, DC 20591

Mr. Calvin J. Cruz Textile Fibers Dept. E.I. Dupont deNemours & Co., Inc. Wilmington, Delaware 19898

Dr. C. Perry Bankston Energy and Materials Research Sec. Jet Propulsion Laboratory 4800 Oak Grove Drive Pasadena, California 91103

Mr. Joseph A. Krist Athol Manufacturing Corporation 1350 Broadway New York, New York 10018

Mr. W. G. Dye Director of Engineering Fairchild Burns Company 1455 Fairchild Drive Winston Salem, NC 27023 Mr. Peter Meiklem Civil Air Attach's (Safety) British Embassy 3100 Massachusetts Ave. NW Washington, DC 20008

Dr. H. R. Dvorak Wesson and Associates, Inc. 510 South Webster Postal Box 1082 Norman, OK 73070

Mr. Erich Feldkirchner Airbus Insustrie Headquarters, BP No. 33 31700 Blagnac, France

Ms. Diane Boulavsky American Textile Mfgrs. Institute 1101 Connecticut Ave. NW Suite 350 Washington, DC 20036

Mr. Gregory Smith B.F. Goodrich Technical Center P.O. Box 122 Avon Lake, Ohio 44012

Mr. George M. Johnson Chief Chemist Pan American Airways, Inc. Bldg. 208 Room 2228 J F Kennedy Int'l Airport Jamaica, New York 11430

Dr. Lloyd H. Back Energy and Materials Research Sec. Jet Propulsion Laboratory 4800 Oak Grove Drive Pasadena, California 91103

Dr. A. Carlos Fernandez-Pello Mechanical Engineering Department University of California, Berkely Berkely, California 9420

Mr. S. F. Taylor College of Aeronautics Cranfield Institute of Technology Cranfield, Bedford MK30AL England Mr. William R. Kane System Engineering Group ASD/ENFEF Wright-Patterson AFB, Ohio 45433

Mr. A. J. Christopher Royal Aircraft Establishment Materials Department South Farnborough Hants, England

Manager
Flight Attendant Training & Standard
Western Airlines
6060 Avion Drive
Los Angeles, California 90009

Mr. Everett A. Tustin Boeing Commerical Airplane Company P.O. Box 3707, M/S GF-26 Seattle, Washington 98124

Mr. R. G. Clodfelter AFWAL/POSH Wright-Patterson AFB Ohio 45433

Dr. Edwin Smith Ohio State University 140 W. 19th Avenue Columbus, Ohio 43214

Mr. Walter Perkowski The Boeing Company Commercial Airplane Group P.O. Box 3707, MS/73-43 Seattle, Washinton 98124

Mr. William Snoddy American Airlines P.O. Box 51009 Mail Stop #10 Tulsa, Oklahoma 74151

Mrs. Charlotte Gebhart Rohm & Haas Company Independence Mall West Philadelphia, PA 19105 Wm. Kirkham, Phd., Md, AAC-144 DOT/FAA/ CAMI Aeronautical Center P.O. Box 25082 Oklahoma City, Oklahoma 73125

Mr. Henry J. Roux Product Fire Performance Armstrong World Industries, Inc. Lancaster, PA 17604

Mr. John Ed Ryan National Forest Products Assoc. 50 North Franklin Turnpike P.O. Box 314 Hohokus, New Jersey 07423

C. M. Sliepcevich Flame Dynamics Laboratory University of Oklahoma 1215 Westheimer Street Norman, Oaklahoma 73069

Mr. Louis Frisco
Wire & Cable Division
Raychem Corp.
300 Constitution Drive
Menlo Park, California 94205

Dr. John A. Parker Chemical Research Projects Office NASA/AMES Research Center M.S. 223-6 Moffett Field, California, 94035

Bernard Grendahl, Mgr. Tech. Service Aerospace Division Universal Oil Products Company Bantam, Conn. 06750

A. Tewarson FMRC 1151 Boston-Providence T'Pke Norwood, Mass. 02062

Dr. Rosalind C. Anderson Arthur D. Little, Inc. Acorn Park Cambridge, Mass. 02140

Mr. Matthew Finucane Aviation Consumer Action Project P.O. Box 19029 Washington, DC 20036

Mr. Leo Fisher Crest Foam 100 Carol Place Moonachie, NJ 07074

Mr. Philip J. DiNenno Professional Loss Control, Inc. P.O. Box 446 Oak Ridge, TN 37830

Mr. James A. Milke
Department of Fire Protection
Engineering
University of Maryland
College Park, MD 20742

Mr. John P. Reese Aerospace Industries Association of America, Inc. 1725 Desales Street, N.W. Washington, DC 20036

Mr. Jim Brown
General Dynamics Electric Boat Div.
Station CG2
Eastern Point Road
Groton, Conn. 06340

Mr. John R. Powers
Delta Airlines, Inc.
Hartsfield Atlanta
International Airport
Atlanta, Georgia 30320

Mr. S. M. Hooper Eastern Airlines Miami International Airport Miami, Florida 33148

Dr. Charles P. Lazzara US Bureau of Mines Pgh. Research Center P.O. Box 18070 Pittsburgh, PA 15236 Dr. James G. Ouintiere National Bureau of Standards Bldg. 224, Room B-356 Washington, DC 20234

Mr. Stan Martin & Assoc. 860 Vista Drive Redwood City, California 94062

Mr. A. L. Bridgman General Electric Company Plastics Technology Department 1 Plastics Avenue Pittsfield, MA 01201

Mr. Walter T. Clark Jr. Clark Engineering Service 312 E. Main Street Lancaster, Texas 75146

Commanding General
U.S. Army Test & Evaluation
Command
Attn: DRSTE-AD-A (D. Conley)
Aberdeen Proving Ground, MD 21005

Mr. Charles Macaluss U.S. Testing 5555 Telegraph Road Los Angeles, CA 90040

Mr. Steve Waldrip Republic Airlines 7500 Airline Drive Minneapolis, Minnesota 55450

T. F. Laughlin, Jr. Lockheed-California Company D/98-01, B/90-4, A-1 P.O. Box 551 Burbank, California 91520

Kirke Comstock
Manager of Interior Engineering
United Airlines Maint. Oper. Center
Engineering Department
San Francisco International Airport
San Francisco, California 94128
A-8

Dr. John Leverton Civil Regulations Manager Civil Business Group Westland Helicopters, LTD. Yeovil, BA20 2YB Somerset, England

Dr. Dale G. Onderak John Schneller & Associates 6019 Powdermill Road Kent, Ohio 44240

Mr. Mike Bauccio
U.S. Army Aviation R&D Command
AVSCOM/DRSAV-NS
St. Louis Missouri 63120

Mr. Vyto Babrauskas National Bureau of Standards Bldg. 224, Room A-345 Washington, DC 20234

Mr. Pascal Dranitsaris Ontario Research Foundation Sheridan Park Research Community Mississauga, Ontario, Canada L5K1B3

Mr. V. W. Ballenger Director, Engineering and Maint. Air Transport Association 1709 New York Avenue, N.W. Washington, DC 20006

Mr. William K. Greer General Electric Company 1 Plastics Avenue Pittsfield, Massachusetts 01201 D. A. Radice Manager, Flexible Sales CPR Division of Upjohn Company 555 Alaska Avenue Torrence, California 90503 1222

POSSESSI PROPERTY BEOSESSES

Distance of the

Mr. Micheal Tyler Aviation Safety Bureau Transport Canada Ottawa, Ontario, Canada KIAON8

Mr. Charles W. McGuire Department of Transportation 400 7th Street S.W. Washington, DC 70590

Mr. A. T. Peacock Douglas Aircraft Company Internal Mail Code 36-41 3855 Lakewood Blvd. Long Beach, California 90846

Mr. Eric W. Simmons Ontario Research Foundation Sheridan Park Research Community Mississauga, Ontario, Canada L5K1B3

Mr. James H. Keeler General Electric Company 1 Plastics Avenue Pittsfield, Massachusetts 01201

END DATE F11MED 8-88 DTIC